

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1505210  
Exposure Number: 00  
Multi-Agency IC#: A1513547 15-045157 00122060  
Incident Date: 05/05/15  
Dispatch Time: 23:09:20  
Arrival Time: 23:16:00  
Controlled Time: 23:40:31  
Ending Time: 12:55:33  
First-In Company: GE2  
District: G2218  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: W911  
Type of Weather:  
Air Temperature: 58  
Address, CSZ: 11782 LORALEEN ST  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Salvage & overhaul  
Actions Taken 3: Investigate  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 10  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$300,000  
Content Losses: \$10,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: 1 or 2 family dwelling  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved: 2  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin Construction/renovation area  
Heat Source: Undetermined  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Cause under investigation  
Contributing Factors 1: Undetermined  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: None  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status: Enclosed building  
# St Above Grnd: Under construction  
# St Below Grnd: 2

## INCIDENT REPORT

-----

Main Floor Size: 0  
Fire Origin: 2500  
Extent of Flame: Construction/renovation area  
Number of Stories Damage: Beyond building of origin  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys: Undetermined  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors: Unknown  
Detector Type:  
Det. Power Supply:  
Det. Operation:  
Det. Effectiveness:  
Det. Failure Reason:

-----

## ARSON

-----

Agency Name:  
Address:  
City:  
State:  
Zip:  
Phone:  
Their Case No.  
Their ORI:  
Their FID:  
Their FDID:  
Case Status:  
Avail of Mat:  
Motivation Factors 1:  
Motivation Factors 2:  
Motivation Factors 3:  
Group Involvement 1:  
Group Involvement 2:  
Group Involvement 3:  
Entry Method:  
Extent of Fire:  
Container:  
Ignit Device:  
Fuel:  
Other Inv Info 1:  
Other Inv Info 2:  
Other Inv Info 3:  
Property Ownership:  
Int Observations 1:

## INCIDENT REPORT

Int Observations 2:  
Int Observations 3:  
Lab Used 1:  
Lab Used 2:  
Lab used 3:

## COMMENTS

\*\*\*\*\* GE2 \*\*\*\*\*

## FIRE - Structure Fire

GE2 responded as part of a structure assignment to a reported house fire at the intersection of Ferris Ln. & Loreleen St. GE2 arrived at 11872 Loreleen & found a two story house in the framing stage of construction that was completely engulfed in flames, reaching approximately 40' - 50' feet vertically & spanning the entire width of the lot. There was direct flame impingement on neighboring properties, including the exposure at 11772 Loreleen that had already ignited. GE2 was spotted a safe distance from the fire due to its intensity & the weakened power lines that had sustained direct flame contact. I reported the initial conditions to responding units, immediately requested a second alarm & initiated fire attack with the objective of reducing the fire's intensity to facilitate evacuations & protect exposures. Command was deferred to the next arriving unit & we secured our own initial water supply.

An exposure line was pulled from GE2 to the front of 11772 Loreleen to protect the structure from further flame impingement and to hold the fire to the lot of origin. GE2's deck gun was put into service with a smooth bore nozzle for maximum reach.

GE5 arrived on scene, augmented our water supply, established Loreleen Command & assigned GE2 to Fire Attack Group. Edison was requested to respond & disconnect power in the area due to the possibility that the power lines would fall. AE4 was assigned to Division B with the objective of evacuation & exposure protection. Area evacuations were accomplished by AE4 & GGPD.

GB1 arrived on scene & assumed command, requested a third alarm, assigned GE5 to Safety and assigned GT1, GE7 & GE6 to Division D. GT1 placed its elevated stream into service on the A / D side. AB2 eventually assumed Division B & AT6 was assigned RIC.

GE1 was assigned to assess a reported exposure fire at 9261 Florence Ln. GE1 investigated & reported that the residence was not on fire. All subsequent arriving units were assigned in an effort to protect exposures on the A, B & D side of the fire -- there was no exposure risk on the C side.

After initial knockdown, all units kept a safe distance from the energized power lines in the event that they would fall. Hose streams were shutdown & only used to keep flare ups in check. Once Edison had disconnected the

INCIDENT REPORT

---

power, the pole was extinguished & firefighting activities resumed.

A resident in the neighborhood reported a fire in an adjacent neighborhood on the C side of the incident and on the other side of the OCTA right of way. HE41 was dispatched & extinguished a bush fire in the backyard of 9331 Skylark Blvd. (Inc.G1505215).

Lengthy overhaul was accomplished with low concentration class B foam and without entering the weakened structure.

The exposure fire at 11772 Loreleen was confirmed to be extinguished. The occupants declined Red Cross services, stating that they had a place to stay. Utilities were disconnected from the home & it was secured using normal door locks since no forcible entry had occurred.

The house under construction at 11872 Loreleen was a total loss. 11772 Loreleen sustained fire, smoke, water & physical damage. A vehicle parked in the driveway was exposed to intense heat resulting in damage to the front of the vehicle, its right side and interior.

The fire was confirmed to be completely extinguished & we cleared the scene. No injuries an no loss of life were reported. Edison remained on scene to complete power line & pole repairs.

Fire cause investigation was conducted by Investigators Kuhlman & Wilkins. Refer to their report for the details of the investigation.

Capt. Niblo

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1505210  
Exposure Number: 01  
Multi-Agency IC#:   
Incident Date: 05/05/15  
Dispatch Time: 23:09:20  
Arrival Time: 23:16:00  
Controlled Time: 23:40:31  
Ending Time: 12:55:33  
First-In Company: GE2  
District: G2218  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: W911  
Type of Weather:   
Air Temperature: 58  
Address, CSZ: 11772 LORALEEN ST  
Census Tract: 0.00  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Salvage & overhaul  
Actions Taken 3:   
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 10  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$75,000  
Content Losses: \$15,000  
Property Value:   
Contents Value:   
Insurance Co:   
Building Ins:   
Mixed Prop Use:   
Property Use: 1 or 2 family dwelling  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc: N  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved: 0  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin Construction/renovation area  
Heat Source: Heat from direct flame, convection curre  
First Item: Exterior roof covering, surface, finish  
Confined to Object: Sawn wood, including all finished lumber  
Material Type: Sawn wood  
Factor Causing:  
Contributing Factors 1: Exposure fire  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: None  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status: Enclosed building  
# St Above Grnd: Occupied and operating  
# St Below Grnd: 1

## INCIDENT REPORT

-----

Main Floor Size: 0  
Fire Origin: 1500  
Extent of Flame: Construction/renovation area  
Number of Stories Damage: Confined to room of origin  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys: None Present  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors: Unknown  
Detector Type:  
Det. Power Supply:  
Det. Operation:  
Det. Effectiveness:  
Det. Failure Reason:

-----

## ARSON

-----

Agency Name:  
Address:  
City:  
State:  
Zip:  
Phone:  
Their Case No.  
Their ORI:  
Their FID:  
Their FDID:  
Case Status:  
Avail of Mat:  
Motivation Factors 1:  
Motivation Factors 2:  
Motivation Factors 3:  
Group Involvement 1:  
Group Involvement 2:  
Group Involvement 3:  
Entry Method:  
Extent of Fire:  
Container:  
Ignit Device:  
Fuel:  
Other Inv Info 1:  
Other Inv Info 2:  
Other Inv Info 3:  
Property Ownership:  
Int Observations 1:



## INCIDENT REPORT

Int Observations 2:  
Int Observations 3:  
Lab Used 1:  
Lab Used 2:  
Lab used 3:

## COMMENTS

\*\*\*\*\* GE2 \*\*\*\*\*

## FIRE - Exposure Fire

This address is the exposure fire related to the structure fire at 11872 Loreleen St. AE4 was assigned to protect this exposure and extinguished fire that had spread to the south side from the main fire as well as confirm that there was no interior extension. The property received fire, smoke, water & physical damage. A vehicle parked in the driveway was exposed to intense heat resulting in damage to the front of the vehicle, its right side and interior.

The occupants were displaced but declined Red Cross services, stating that they had a place to stay. Utilities were disconnected from the home & it was secured using normal door locks since no forcible entry had occurred.

Refer to G1505210-00 for the full report on overall incident actions.

Capt. Niblo