

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1505325
Exposure Number: 00
Multi-Agency IC#: A1513952 15-046487 00125864
Incident Date: 05/09/15
Dispatch Time: 22:12:56
Arrival Time: 22:18:01
Controlled Time: 22:28:15
Ending Time: 00:31:40
First-In Company: GE7
District: G2520
Incident Type: Fires in structures other than in a building
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 59
Address, CSZ: 10231 DAKOTA AV
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 4
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$100,000
Content Losses: \$50,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Residential, other
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 0
Acres Burned:
On-Site Mat/Stor:
Area of Origin: Other
Heat Source: Candle
First Item: Cabinetry (including built-in)
Confined to Object: Wood or paper, processed, other
Material Type: Insufficient Information
Factor Causing: Unintentional
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Undetermined
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Other power source
Equip Portability: Portable
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Structure type, other
St Above Grnd:
St Below Grnd:

INCIDENT REPORT

Main Floor Size:
Fire Origin:
Extent of Flame: Other
Number of Stories Damaged By Flame
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys:
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors:
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE7 *****

FIRE
RESIDENTIAL

GE7 RESPONDED TO A RESIDENTIAL BEDROOM FIRE. ON ARRIVAL, GE7 ENCOUNTERED A SINGLE STORY RESIDENTIAL WITH SMOKE PRESENT OUT THE FRONT DOOR. GE7 DEPLOYED HANDLINES AND ATTACKED THE FIRE. THE FIRE WAS LOCATED IN THE REAR BEDROOM OF THE HOUSE. ENTRY WAS MADE BY GE7 CREW AND A KNOCKDOWN OF FIRE WAS ACHIEVED. ADDITIONAL RESOURCES WERE USED ON SCENE TO EXTINGUISH AND VENTILATE THE FIRE. TWO ELDERLY LADIES LIVES IN THE HOUSE. BOTH WERE EVACUATED PRIOR TO GE7 ARRIVAL BY NEIGHBORS. BOTH WERE TREATED ON SCENE AND TRANSPORTED TO GGMC FOR SMOKE INHALATION. CE66 WAS THE MEDICAL UNIT TREATING PT'S.

ON FURTHER INVESTIGATION AND QUESTION OF HOMEOWNERS, IT WAS DETERMINED THAT THE FIRE WAS STARTED BY A UNATTENDED CANDLE IN THE REAR BEDROOM OF THE HOUSE WHERE THE FIRE WAS CONCENTRATED. THIS FACT WAS CONFIRMED BY ONE OF THE HOME RESIDENTS. BUSTOS, SOCORRO STATED THAT SHE HAD LEFT A CANDLE IN THE FIRE ROOM ON TOP OF A DRESSER BY A WINDOW AND LATER HEARD A NOISE AS LIKE SOMETHING HAD FALLEN. SHORTLY AFTER THAT THERE HAS SMOKE THROUGHT THE HOUSE. SHE WENT TO SEE WHAT THE NOICE WAS AND SAW FIRE ON THE DRESSER IN THE INVOLVED ROOM.

RESIDENTS SOCORRO BUSTOS
OFLIA MANCERA

PROPERTY WAS RELEASED TO NEIGHBORS. NEIGHBORS WERE ACTING AS HOME OWNER'S

INCIDENT REPORT

REPRESENTATIVE. THE PROPERTY WAS LOCKED AND SECURED.

ACOSTA, CAPT