

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1511171
Exposure Number: 00
Multi-Agency IC#: A1529773 15-098428 00285199
Incident Date: 09/28/15
Dispatch Time: 21:36:32
Arrival Time: 21:42:03
Controlled Time: 21:49:17
Ending Time: 00:54:37
First-In Company: GT1
District: G2421
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 73
Address, CSZ: 12939 MAIN ST
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Fire control or extinguishment, other
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 10
Fire Svs Injury: 1
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$80,000
Content Losses: \$40,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Restaurant or cafeteria
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved:
Acres Burned:
On-Site Mat/Stor:
Area of Origin: Cooking area, kitchen
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Factors contributing to ignition, other
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Kitchen & cooking equipment, other
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Natural gas or other lighter-than-air ga
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 1000
Extent of Flame: Cooking area, kitchen
Number of Stories Damage: Confined to building of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:
Int Observations 3:
Lab Used 1:
Lab Used 2:
Lab used 3:

PATIENT REPORT

Name Unknown (OC-MEDS Import)
DOB, Age, Sex 40 Male
Address, CSZ:
Country:
Telephone:
Driver's Lic#:
SS Number:
Employer:
Emp Phone:
Relative:
Rel Phone:
Insurance:
Police #:
Billing Care:
Status:
Transported To:
Transported By:
ALS Intervention:
Escorted:
Procedures Used 1: No treatment
Procedures Used 2:
Procedures Used 3:
Arrived Date:
Transport Date:
Assessment:
Other Factors:
Human Factors 1:
Human Factors 2:
Human Factors 3:
Cause of Injury:
Body Site of Injury 1:
Body Site of Injury 2:
Body Site of Injury:
Safety Equipment:
Cardiac Arrest:
CA Prearrival:
CA Init Rhythm:
Initial Care Level:
Highest Care Level:
Patient Status:
Pulse on Transfer:
Disposition: Non-FD transport

INCIDENT REPORT

COMMENTS

***** GT1 *****

STRUCTURE FIRE
RESTAURANT/KITCHEN FIRE

GE7 WAS DISPATCHED TO A REPORTED FLAMES SEEN FROM THE ADDRESS ABOVE. GB1 WAS ON SCENE FIRST AND ASSIGNED GE7 TO THE FRONT OF THE BUILDING, ALPHA SIDE, TO MAKE ENTRY AND ATTEMPT TO LOCATE THE FIRE. AFTER GE7 CREW PERFORMED FORCIBLE ENTRY INTO THE RESTAURANT, GE7 ADVANCED A HOSE LINE INTO THE KITCHEN AREA WHERE FLAMES WERE VISIBLE ON THE STOVE GRILL AREA. THE FIRE WAS EXTINGUISHED AND ADDITIONAL RESOURCES WERE UTILIZED IN THE EVENT. GE7 WAS ASSIGNED "INTERIOR" GE1 AND GE6 WERE ASSIGNED TO WORK FOR INTERIOR. AFTER INITIAL FIRE KNOCKDOWN, THERE WAS SMOKE PRODUCTION FROM WHAT APPEARED TO BE A VOID/ATTIC SPACE. VENTILATION CREWS COORDINATED WITH INTERIOR FIRE ATTACK AND THE FIRE WAS LOCATED IN A VOID SPACE IN BETWEEN TWO ATTIC SPACES. RESOURCES WERE UTILIZED TO SALVAGE AND OVERHAUL. GROVE INVESTIGATORS WERE CALLED OUT TO PERFORM AN INVESTIGATION OF THE FIRE. IT APPEARS THAT THE FIRE WAS CONFINED TO THE KITCHEN AREA AND THE ATTIC/VOID SPACE ABOVE THE STOVES. AFTER OVERHAUL, THE PROPERTY WAS RELEASED TO BUSINESS OWNER AND ALL APPROPRIATE PAPERWORK WERE COMPLETED.

FIRE/ENGINEER CLEARWATER WAS HURT IN THE FIRE VENTILATION PHASE OF THE EVENT. A KNEE PROBLEM WAS REPORTED TO APPROPRIATE PERSONNEL.

ACOSTA, A CAPT.

FIRE SERVICE CASUALTY

Casualty No:
ID Number:
Name:
Sex: Male
Status:
DOB:
Responses:
Assignment:
Date & Time: 23:00:00
Physical Condition:
Severity: Moderate severity, 1
Taken to:
Activity:

INCIDENT REPORT

Symptom:
Area of Body:
Cause:
Contributing Factors:
Object Involved:
Where Injured:
Story Injured:
Specific:
Vehicle Type:
Equipment Failed:

CASUALTY COMMENTS

FIREFIGHTER/ENGINEER WAS HURT DURING VENTILATION OPERATIONS WITH POSSIBLY A KNEE INURY. FF WAS RELIEVED AND SENT TO DR/HOME FOR EVAL