

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1511171  
Exposure Number: 00  
Multi-Agency IC#: A1529773 15-098428 00285199  
Incident Date: 09/28/15  
Dispatch Time: 21:36:32  
Arrival Time: 21:42:03  
Controlled Time: 21:49:17  
Ending Time: 00:54:37  
First-In Company: GT1  
District: G2421  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:  
Air Temperature: 73  
Address, CSZ: 12939 MAIN ST  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Fire control or extinguishment, other  
Actions Taken 2:  
Actions Taken 3:  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 0  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 10  
Fire Svs Injury: 1  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$80,000  
Content Losses: \$40,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: Restaurant or cafeteria  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## COMMENTS

\*\*\*\*\* GT1 \*\*\*\*\*

STRUCTURE FIRE  
RESTAURANT/KITCHEN FIRE

GE7 WAS DISPATCHED TO A REPORTED FLAMES SEEN FROM THE ADDRESS ABOVE. GB1 WAS ON SCENE FIRST AND ASSIGNED GE7 TO THE FRONT OF THE BUILDING, ALPHA SIDE, TO MAKE ENTRY AND ATTEMPT TO LOCATE THE FIRE. AFTER GE7 CREW PERFORMED FORCIBLE ENTRY INTO THE RESTAURANT, GE7 ADVANCED A HOSE LINE INTO THE KITCHEN AREA WHERE FLAMES WERE VISIBLE ON THE STOVE GRILL AREA. THE FIRE WAS EXTINGUISHED AND ADDITIONAL RESOURCES WERE UTILIZED IN THE EVENT. GE7 WAS ASSIGNED "INTERIOR" GE1 AND GE6 WERE ASSIGNED TO WORK FOR INTERIOR. AFTER INITIAL FIRE KNOCKDOWN, THERE WAS SMOKE PRODUCTION FROM WHAT APPEARED TO BE A VOID/ATTIC SPACE. VENTILATION CREWS COORDINATED WITH INTERIOR FIRE ATTACK AND THE FIRE WAS LOCATED IN A VOID SPACE IN BETWEEN TWO ATTIC SPACES. RESOURCES WERE UTILIZED TO SALVAGE AND OVERHAUL. GROVE INVESTIGATORS WERE CALLED OUT TO PERFORM AN INVESTIGATION OF THE FIRE. IT APPEARS THAT THE FIRE WAS CONFINED TO THE KITCHEN AREA AND THE ATTIC/VOID SPACE ABOVE THE STOVES. AFTER OVERHAUL, THE PROPERTY WAS RELEASED TO BUSINESS OWNER AND ALL APPROPRIATE PAPERWORK WERE COMPLETED.

FIRE/ENGINEER CLEARWATER WAS HURT IN THE FIRE VENTILATION PHASE OF THE EVENT. A KNEE PROBLEM WAS REPORTED TO APPROPRIATE PERSONNEL.

ACOSTA, A CAPT.