

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1513801  
Exposure Number: 00  
Multi-Agency IC#: A1537047 15-123590  
Incident Date: 12/05/15  
Dispatch Time: 11:17:20  
Arrival Time: 11:20:47  
Controlled Time: 11:24:34  
Ending Time: 13:45:41  
First-In Company: GE1  
District: G2422  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:  
Air Temperature: 61  
Address, CSZ: 12692 EIGHTH ST  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Salvage & overhaul  
Actions Taken 3: Investigate  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 4  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$20,000  
Content Losses: \$10,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: 1 or 2 family dwelling  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved: 1  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin Function areas, other  
Heat Source: Undetermined  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Unintentional  
Contributing Factors 1: None  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: Undetermined  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source: Electrical line voltage (> 50 volts)  
Equip Portability: Stationary  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status: Enclosed building  
# St Above Grnd: Occupied and operating  
# St Below Grnd: 1

## INCIDENT REPORT

-----

Main Floor Size: 0  
Fire Origin: 1000  
Extent of Flame: Function areas, other  
Number of Stories Damage: Confined to room of origin  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys: None Present  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors: Present  
Detector Type: Smoke  
Det. Power Supply: Undetermined  
Det. Operation: Detector operated  
Det. Effectiveness: Alerted occupants, occupants responded  
Det. Failure Reason:

-----

## COMMENTS

-----

\*\*\*\*\* GE1 \*\*\*\*\*

## STRUCTURE FIRE

RESPONDED ON A STRUCTURE FIRE. UPON ARRIVAL FOUND FIRE COMING OUT OF THE FRONT DOOR AND A WINDOW TO THE FRONT OF THE HOUSE. GROVE E1 ATTACKED THE FIRE WITH A PRECONNECTED HOSELINE AND ON BOARD WATER. GT1 PROVIDED VERTICAL VENTILATION. THE FIRE WAS EXTINGUISHED AND HELD TO THE ROOM OF ORIGIN. THE REST OF THE RESIDENCE SUSTAINED SMOKE DAMAGE.

FIRE WAS INVESTIGATED BY CAPTAIN WILKINS TO DETERMINE CAUSE AND ORIGIN. RESIDENT STATED THAT SHE HEARD A POPPING NOISE AND WENT TO THE FRONT ROOM AND SAW SPARKS LANDING ON HER DRAPES. SHE STATED THAT THE DRAPES CAUGHT FIRE AND SHE YELLED FOR HELP. RESIDENT ALSO STATED THAT SHE HEARD HER SMOKE ALARM SOUNDING. THE ORIGIN OF THE FIRE WAS DETERMINED TO BE THE ROOM IN THE SOUTH WEST CORNER OF THE BUILDING. THE CAUSE OF THE FIRE WAS UNDETERMINED BUT PER THE WITNESS STATEMENT AND MY INVESTIGATION, THE FIRE WAS DETERMINED TO BE ACCIDENTAL IN NATURE AND MOST PROBABLE CAUSE WAS AN UNSPECIFIED ELECTRICAL FAILURE.

CAPTAIN JEFFREY LEE WILKINS

