

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1500131
Exposure Number: 00
Multi-Agency IC#: 15-001248
Incident Date: 01/04/15
Dispatch Time: 11:53:49
Arrival Time: 12:01:29
Controlled Time: 12:20:19
Ending Time: 14:41:59
First-In Company: GE2
District: G2517
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 47
Address, CSZ: 13164 FERNDALE DR
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Salvage & overhaul
Actions Taken 3: Investigate
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 4
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$100,000
Content Losses: \$10,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Multifamily dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Heating room or area, water heater area
Heat Source: Heat from powered equipment, other
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Heater, excluding catalytic and oil-fill
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Natural gas or other lighter-than-air ga
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 2

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 1000
Extent of Flame: Heating room or area, water heater area
Number of Stories Damage: Confined to floor of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE2 *****

FIRE - Structure Fire

Responded as part of a structure assignment to a condominium complex. Upon arrival, GE2 observed smoke coming from the roof of a two story unit. Command was deferred to the next arriving unit while GE2 pulled a preconnect through the garage of a neighboring unit & around to the front door of 13164 Ferndale Dr. Subsequent arriving units checked the exposures on either side & supplemented the fire attack effort.

A fire in the attic area was found that spread from a forced air unit closet. A primary all-clear was confirmed. GT1 provided vertical ventilation. The fire was contained to the closet & attic area directly above.

Extensive salvage & overhaul occurred inside 13164 Ferndale due to the amount of water used. The fire was confirmed to be extinguished both visually & with the use of a thermal imaging camera.

Homeowner's association representatives were located & advised to contact their insurance company for board up services. Property release forms were explained to & understood by the occupants of 13162, 13164 & 13166 Ferndale. All displaced occupants were offered Red Cross services.

The origin appeared to be somewhere within the forced air unit. Fire cause was investigated by Investigator Strohm.

INCIDENT REPORT

Capt. Niblo