

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1610117  
Exposure Number: 00  
Multi-Agency IC#:   
Incident Date: 09/03/16  
Dispatch Time: 22:22:51  
Arrival Time: 22:27:21  
Controlled Time:   
Ending Time: 22:57:41  
First-In Company: GE5  
District: G2519  
Incident Type: Passenger vehicle fire  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:   
Air Temperature: 68  
Address, CSZ: 9754 GARDEN GROVE BL  
Census Tract:   
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2:   
Actions Taken 3:   
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 0  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 1  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$1,000  
Content Losses: \$0  
Property Value:   
Contents Value:   
Insurance Co:   
Building Ins:   
Mixed Prop Use:   
Property Use: Vehicle parking area  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved:  
Acres Burned:  
On-Site Mat/Stor: Autos, trucks, buses, recreational vehic  
Area of Origin Fuel tank, fuel line  
Heat Source: Undetermined  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Intentional  
Contributing Factors 1: Undetermined  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: None  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv: Not involved in ignition, but burned  
Mobile Prop Type: Automobile, passenger car, ambulance, ra  
Mobile Prop Make: Toyota  
Mobile Prop Model: TUNDRA  
Mobile Prop Year: 2014  
Mobile Prop Lic. Plate: 77110J1  
Mobile Prop Lic. State: CA  
Mobile Prop VIN Number: 5TFRM5F12EX077539  
Mobile Prop Stolen?: N  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status:  
# St Above Grnd:  
# St Below Grnd:

INCIDENT REPORT

-----

Main Floor Size:  
 Fire Origin:  
 Extent of Flame: Fuel tank, fuel line  
 Number of Stories Damaged By Flame  
 Minor:  
 Sign:  
 Heavy;  
 Extreme:  
 Auto Ext Sys:  
 AES Type:  
 AES Operation:  
 # Sprinkler Heads:  
 AES Failure Reason:  
 Detectors:  
 Detector Type:  
 Det. Power Supply:  
 Det. Operation:  
 Det. Effectiveness:  
 Det. Failure Reason:

-----  
COMMENTS  
-----

\*\*\*\*\* GE5 \*\*\*\*\*

VEHICLE FIRE

RESPONDED TO VEHICLE FIRE WITH GGPD ON SCENE. THIS WAS A PICKUP TRUCK PARKED IN THE SOUTH END OF STRIP CENTER. TRUCK HAD SMALL FIRE SHOWING FROM ABOVE THE LEFT REAR TIRE, ALONG WITH EFFECTS OF FIRE SHOWING ABOVE FUEL FILL AREA. FUEL FILL CAP AND COVER WERE LOCATED ON THE GROUND NEXT TO TRUCK. TANK WATER USED TO EXTINGUISH FIRE. TRUCK OWNER STATED THAT HE HAD NOT HAD ANY ISSUES WITH THE VEHICLE, AND HAD PARKED IT THERE APPROXIMATELY THREE HOURS EARLIER WHEN HE WENT INTO HIS BUSINESS LOCATED ADJACENT TO PARKING LOT. GGPD TOOK REPORT AND PICTURES OF TRUCK, AND WAS FOLLOWING UP WITH ANY EVIDENCE POSSIBLY FOUND FROM CAMERAS MOUNTED IN THE GENERAL VICINITY.

CAPT. ABRAHAMSON

