

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1610543
Exposure Number: 00
Multi-Agency IC#: 16-096880
Incident Date: 09/13/16
Dispatch Time: 17:48:29
Arrival Time: 17:52:36
Controlled Time: 17:58:42
Ending Time: 19:38:18
First-In Company: GE7
District: G2721
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 72
Address, CSZ: THE BRITTANY, 10500 WESTMINSTE
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Salvage & overhaul
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 4
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$20,000
Content Losses: \$15,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Multifamily dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Vehicle area, other
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Undetermined
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Solid fuel, other
Equip Portability: Portable
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 400
Extent of Flame: Vehicle area, other
Number of Stories Damage: Confined to room of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Not present
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE7 *****

STRUCTURE FIRE

GE7 RESPONDED TO A GARAGE FIRE AT 10500 WESTMINSTER. ON ARRIVAL GE7 ANNOUNCED A WORKING GARAGE FIRE EXTENDING TO THE ADJACENT GARAGE ON THE DELTA SIDE. GE7 WENT INTO ATTACK MODE AND KNOCKED THE FIRE DOWN IN A FEW MINUTES. BOTH GARAGES WERE OVERHAULED DUE TO SMOKE AND WATER DAMAGE.

ARSON INVESTIGATOR KUHLMAN INTERVIEWED THE TENANT BUT WAS UNABLE TO DETERMINE CAUSE.

EDISON WAS CALLED OUT TO ENSURE POWER WAS TURNED OFF TO THE GARAGES.

UNITS INVOLVED:GB1, GE1 CE78 GT1 AND GM1

CAPT FELLNER

