

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1700789
Exposure Number: 00
Multi-Agency IC#: 17-006881 H1701001
Incident Date: 01/18/17
Dispatch Time: 05:52:42
Arrival Time: 05:57:28
Controlled Time: 06:23:07
Ending Time: 08:54:21
First-In Company: GE5
District: G2417
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 44
Address, CSZ: 12732 DALE ST
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 3
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$250,000
Content Losses: \$25,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Bedroom - < 5 persons; included are jail or prison
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Cause undetermined after investigation
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Undetermined
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Electrical line voltage (> 50 volts)
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 150
Extent of Flame: Bedroom - < 5 persons; included are jail
Number of Stories Damage: Confined to floor of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:
Int Observations 3:
Lab Used 1:
Lab Used 2:
Lab used 3:

COMMENTS

***** GE5 *****

STRUCTURE FIRE-RESIDENTIAL ·
EXTINGUISHED A HOUSE FIRE WITH A 150' 1 3/4" PRE-CONNECT HOSE LINE. FIRE
APPEARED TO START IN A BACK BEDROOM AND EXTEND THROUGHOUT THE ENTIRE HOUSE.
CAUSE OF FIRE WAS DETERMINED TO BE ACCIDENTAL UNDETERMINED BUT POSSIBLY DUE
TO A PORTABLE LAMP IN THE BEDROOM. GE2,GT1,CE64,CT64,GM1, AND GB1 ASSISTED
WITH COMMAND AND R.E.C.E.O. ON THE FIRE. G.G.P.D. WAS ON SCENE FOR TRAFFIC
CONTROL. RED CROSS RESPONDED FOR OCCUPANT ASSISTANCE/HOUSING. PROPERTY WAS
RELEASED BACK TO THE OWNERS AFTER COMPLETION OF INVESTIGATION. GE5 SECURED.
CAPT. EDNOFF