INCIDENT REPORT

INCIDENT _______ Fire Department: Garden Grove Fire Department Incident Number: G1709133
Exposure Number: 00 Multi-Agency IC#: A1723300 17-086257 Incident Date: 08/07/17 18:20:18 18:28:11 18:45:33 20:02:17 Dispatch Time: Arrival Time: Controlled Time: 18:4
Ending Time: 20:0
First-In Company: GE6 District
Incident Type:
Mutual Aid: G2425 Passenger vehicle fire None Method of Alarm: Telephone Type of Weather: Air Temperature 82 Address, CSZ: 12842 PALM ST Census Tract: Fire Haz Sev Zone: Medium RESOURCES & CASUALTIES ______ Actions Taken 1: Extinguishment by fire service personnel Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: 3 #Apparatus Resp Engine.

#Apparatus Resp Trk: 1

#Apparatus Resp Med: 1

#Apparatus Resp Oth: 1

Fire Svs Injury: 0

Fire Svs Fatal: 0

Non-FS Injury: 0

Non-FS Fatal: 0 Non-FS Fatal: PROPERTY & STUDIES ______ Property Losses: \$30,000 Content Losses: \$1,000 Property Value: Contents Value: Insurance Co:

Property Use: Vehicle parking area Detector

Building Ins: Mixed Prop Use:

INCIDENT REPORT

Hazmat Rel: None Critical Inc: Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units: Bldgs. Involved: Acres Burned:

Autos, trucks, buses, recreational vehic Engine area, running gear, wheel area Heat from powered equipment, other On-Site Mat/Stor: Area of Origin Heat Source:

First Item: Undetermined

Confined to Object:

Material Type:

Factor Causing: Failure of equipment or heat source

Contributing Factors 1: Undetermined

Contributing Factors 2:

Human Factor Cont 1: None

Human Factor Cont 2: Human Factor Cont 3:

Age Sex

Equip Involved: None

Equip Brand: Equip Model:

Equip Serial Number:

Equip Year:

Equip Power Source: Equip Portability:

Mobile Prop Inv:

Involved in ignition and burned Automobile, passenger car, ambulance, ra Mobile Prop Type:

Mobile Prop Make: Honda Mobile Prop Model: Accord Mobile Prop Year: 2013 Mobile Prop Lic. Plate: 7APL650 Mobile Prop Lic. State: CA

Mobile Prop VIN Number: unk Mobile Prop Stolen?: Suppression Factors: None

**** GE6 ****

Fire - Structure Fire

COMMENTS

INCIDENT REPORT

GE6 responded to the above address for structure fire. Upon arrival GE6 found heavy smoke coming from the parking structure of the apartment complex. GE6 went into the attack mode, initiated a primary search and started extinguishing the fire. GE3 came on scene and established command and two-out. GB1 arrived on scene shortly after and took command from GE3, assigned GLF-1 to vent group and AE3 to back up fire attack. Fire was quickly knocked down by fire personnel. Fire was confined to a single vehicle in the rear of the parking structure. Once scene was secure it was released back to the owner's representative. No injuries to civilians or fire personnel.

The fire was investigated by Captain/ Arson Investigator Kuhlman. The fire was confined to the engine compartment of the vehicle. The cause of the fire was unspecified mechanical failure in the engine compartment. Owner of the vehicle stated that he had a gasket valve adjustment recently done to the car at Honda World in the City of Westminster.

Captain Trenholm