## INCIDENT REPORT

\_\_\_\_\_\_ INCIDENT \_\_\_\_\_\_ Fire Department: Garden Grove Fire Department Incident Number: G1511171 Exposure Number: A1529773 15-098428 00285199 09/28/15 Multi-Agency IC#: Incident Date: 21:36:32 21:42:03 21:49:17 00:54:37 Dispatch Time: Arrival Time: Controlled Time: Ending Time: First-In Company: GT1 District
Incident Type:
Mutual Aid: G2421 Building fire None Method of Alarm: E911 Type of Weather: 73 Air Temperature Address, CSZ: Census Tract: 12939 MAIN ST Fire Haz Sev Zone: Medium \_\_\_\_\_\_\_ RESOURCES & CASUALTIES \_\_\_\_\_\_ Actions Taken 1: Fire control or extinguishment, other Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: 0 #Apparatus Resp Trk: 0 #Apparatus Resp Med: 1
#Apparatus Resp Oth: 10
Fire Svs Injury: 1 Fire Svs Fatal: Non-FS Injury: PROPERTY & STUDIES \$80,000 \$40,000 Property Losses: Content Losses: Property Value:

Property Value: Contents Value: Insurance Co: Building Ins: Mixed Prop Use:

Property Use: Restaurant or cafeteria

Detector

## INCIDENT REPORT

Hazmat Rel: None Critical Inc: Special Studies: FIRE/ EXPLOSION SITUATION Residential Units: Bldgs. Involved: Acres Burned: On-Site Mat/Stor: Area of Origin Cooking area, kitchen Undetermined Heat Source: First Item: Undetermined Confined to Object: Material Type: Factor Causing: Unintentional Contributing Factors 1: Factors contributing to ignition, other Contributing Factors 2: Human Factor Cont 1: None Human Factor Cont 2: Human Factor Cont 3: Age Sex Equip Involved: Kitchen & cooking equipment, other Equip Brand: Equip Model: Equip Serial Number: Equip Year: Equip Power Source: Natural gas or other lighter-than-air ga Equip Portability: Stationary Mobile Prop Inv: Mobile Prop Type: Mobile Prop Make: Mobile Prop Model: Mobile Prop Year: Mobile Prop Lic. Plate: Mobile Prop Lic. State: Mobile Prop VIN Number: Mobile Prop Stolen?: Suppression Factors: ARSON

Agency Name: Address:

City: State:

## INCIDENT REPORT

Phone: Their Case No. Their ORI: Their FID: Their FDID: Case Status: Avail of Mat: Motivation Factors 1: Motivation Factors 2: Motivation Factos 3: Group Involvement 1: Group Involvement 2: Group Involvement 3: Entry Method: Extent of Fire: Container: Ignit Device: Fuel: Other Inv Info 1: Other Inv Info 2: Other Inv Info 3: Property Ownership: Int Observations 1: Int Observations 2: Int Observations 3: Lab Used 1: Lab Used 2: Lab used 3:

Zip:

COMMENTS

\*\*\*\*\* GT1 \*\*\*\*\*

STRUCTURE FIRE RESTAURANT/KITCHEN FIRE

GE7 WAS DISPATCHED TO A REPORTED FLAMES SEEN FROM THE ADDRESS ABOVE. GB1 WAS ON SCENE FIRST AND ASSINGED GE7 TO THE FRONT OF THE BUILDING, ALPHA SIDE, TO MAKE ENTRY AND ATTEMPT TO LOCATE THE FIRE. AFTER GE7 CREW PERFORMED FORCIBLE ENTRY INTO THE RESTAURANT, GE7 ADVANCED A HOSE LINE INTO THE KITCHEN AREA WHERE FLAMES WERE VISIBLE ON THE STOVE GRILL AREA. THE FIRE WAS EXTINGUISHED AND ADDITIONAL RESOURCES WERE UTILIZED IN THE EVENT. GE7 WAS ASSIGNED "INTERIOR" GE1 AND GE6 WERE ASSIGNED TO WORK FOR INTERIOR. AFTER INITIAL FIRE KNOCKDOWN, THERE WAS SMOKE PRODUCTION FROM WHAT APPEARED TO BE A VOID/ATTIC SPACE. VENTILATION CREWS COORDINATED WITH INTERIOR FIRE ATTACK AND THE FIRE WAS LOCATED IN A VOID SPACE IN BETWEEN TWO ATTIC SPACES. RESOURCES WERE UTILIZED TO SALVAGE AND OVERHAUL. GROVE INVESTIGATORS WERE

## INCIDENT REPORT

CALLED OUT TO PERFORM AN INVESTIGATION OF THE FIRE. IT APPEARS THAT THE FIRE WAS CONFINED TO THE KITCHEN AREA AND THE ATTIC/VOID SPACE ABOVE THE STOVES. AFTER OVERHAUL, THE PROPERTY WAS RELEASED TO BUSINESS OWNER AND ALL APPROPRIATE PAPERWORK WERE COMPLETED.

FIRE/ENGINEER CLEARWATER WAS HURT IN THE FIRE VENTILATION PHASE OF THE EVENT. A KNEE PROBLEM WAS REPORTED TO APPROPRIATE PERSONNEL.

ACOSTA, A CAPT.