

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1505919
Exposure Number: 00
Multi-Agency IC#: A1515517 15-051573
Incident Date: 05/24/15
Dispatch Time: 11:12:33
Arrival Time: 11:17:04
Controlled Time: 11:21:36
Ending Time: 12:03:51
First-In Company: GE2
District: G2117
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 64
Address, CSZ: 8581 ORANGEWOOD AV
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Salvage & overhaul
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 3
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$500
Content Losses: \$200
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

EMERGENCY MEDICAL SERVICE

Number of Patients:
Billing Care:
Status:
Transported to:
Patients Trans - Fire:
Patients Trans - Amb:

COMMENTS

***** GE2 *****

FIRE - Dryer Fire

Responded as part of a structure assignment to a single family residence on a report of a garage / clothes dryer fire. Upon arrival, GE2 found light smoke coming from the garage & the occupants standing in the front yard. GE2 investigated while holding the assignment.

GE2's firefighter found a bedroom at the back of the garage that was attached to a laundry room. The bedroom was charged with smoke nearly to the floor with high temperatures. GE2 pulled a hoseline, established Orangewood IC, assigned GE5 to Fire Attack, assigned CT64 to Ventilation group and released AE11. GE5 handled utilities & confirmed a primary all clear.

The fire was knocked down & smoke was removed via horizontal ventilation. Ceilings & walls in the laundry room were opened to check for extension. The dryer was removed to the back yard and the fire was confirmed to be out with a thermal imaging camera.

Command was dissolved & units were released. A property release form was explained to & understood by the occupant. Power to the unaffected portion of the residence was restored.

Capt. Niblo