

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1406301
Exposure Number: 00
Multi-Agency IC#: A1418221 14065027 00175747
Incident Date: 07/07/14
Dispatch Time: 22:23:08
Arrival Time: 22:29:43
Controlled Time: 22:44:42
Ending Time: 01:38:19
First-In Company: GE1
District: G2421
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 71
Address, CSZ: 12772 WESTLAKE ST
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Salvage & overhaul
Actions Taken 3: Investigate
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 9
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$200,000
Content Losses: \$75,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 2
Acres Burned:
On-Site Mat/Stor: None
Area of Origin: Courtyard, patio, porch, terrace
Heat Source: Fireworks
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Misuse of material or product, other
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 1400
Extent of Flame: Courtyard, patio, porch, terrace
Number of Stories Damage: Beyond building of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE1 *****

STRUCTURE FIRE

RESPONDED ON A REPORTED STRUCTURE FIRE. UPON ARRIVAL GE1 REPORTED VISIBLE FIRE ON THE SOUTH SIDE OF THE BUILDING. GE1 ATTACKED THE FIRE WITH A PRECONNECTED HOSELINE WITH ON BOARD WATER. GE6 ASSISTED GE1 WITH FIRE EXTINGUISHMENT. GM1 PERFORMED A SEARCH OF THE BUILDING FOR ANY OCCUPANTS, NONE WERE FOUND. GT1 PROVIDED VERTICAL VENTILATION AND TURNED OFF THE UTILITIES. THE FIRE WAS INVESTIGATED BY CAPTAIN WILKINS. FOLLOWING THE INVESTIGATION AND INTERVIEWS OF WITNESSES IT WAS DETERMINED THAT THE MOST LIKELY CAUSE WAS ILLEGAL FIREWORKS. GT1 AND GE1 PERFORMED OVERHAUL. PROPERTY RELEASE FORM WAS EXPLAINED AND SIGNED BY OWNER.

CAPTAIN JEFFREY LEE WILKINS

***** GE7 *****

MEDICAL AID

ALL INFO IMPUTED ON FIRE REPORT ASSIGNED TO GROVE ENG 2

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1406312
Exposure Number: 00
Multi-Agency IC#:
Incident Date: 07/08/14
Dispatch Time: 08:04:04
Arrival Time: 08:08:16
Controlled Time:
Ending Time: 08:52:54
First-In Company: GE1
District: G2421
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: Telephone
Type of Weather:
Air Temperature: 67
Address, CSZ: 12772 WESTLAKE ST
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 4
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$0
Content Losses: \$0
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Undetermined
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Cause under investigation
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Undetermined
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Wood, paper
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Being demolished
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 1300
Extent of Flame: Undetermined
Number of Stories Damage: Confined to building of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: Undetermined
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE1 *****

Fire - Structure

GE1 and multiple units responded to a reported structure fire. Upon arrival GE1 had light smoke to the rear of the structure, investigating. GE1 had a small amount of roofing material smoldering. GE1 and GT1 extinguished the fire and provided overhaul. This was a fire that was handled about 6 hours earlier from another shift. GE1 had the property owner sign a release form. GE1 also had a GG building inspector assess and red tag the home due to a leaning detached chimney. Red cross was provided for the owner and her infant. No injuries.

Captain Hanna