

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1506153
Exposure Number: 00
Multi-Agency IC#:
Incident Date: 05/30/15
Dispatch Time: 06:36:16
Arrival Time: 06:43:32
Controlled Time:
Ending Time: 07:39:45
First-In Company: GE5
District: G2114
Incident Type: Water problem, other
Mutual Aid: None
Method of Alarm: Telephone
Type of Weather:
Air Temperature: 61
Address, CSZ: 11330 MARKON DR
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Shut down system
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 1
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury:
Non-FS Fatal:

PROPERTY & STUDIES

Property Losses:
Content Losses:
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Manufacturing, processing
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved:
Acres Burned:
On-Site Mat/Stor:
Area of Origin
Heat Source:
First Item:
Confined to Object:
Material Type:
Factor Causing:
Contributing Factors 1:
Contributing Factors 2:
Human Factor Cont 1:
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved:
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status:
St Above Grnd:
St Below Grnd:

INCIDENT REPORT

Main Floor Size:
Fire Origin:
Extent of Flame:
Number of Stories Damaged By Flame
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys:
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors:
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE5 *****

SERVICE-INVESTIGATION
ENCOUNTERED A SPRINKLER ACTIVATION IN A FURNITURE WAREHOUSE/WOODSHOP DUE TO
A POSSIBLE TABLESAW/EQUIPMENT FIRE OUT P.T.A. GE5 SHUT DOWN THE SPRINKLER
SYSTEM AND SECURED THE PROPERTY AFTER MULTIPLE ATTEMPTS TO CONTACT THE
BUSINESS OWNER BY G.G.P.D. AND GE5 FAILED. (PHONE WAS NOT ANSWERED). ADJACENT
BUSINESS WAS ADVISED TO NOTIFY THE SPRINKLER CO. TO RESPOND TO PUT THE
SYSTEM BACK IN SERVICE BEFORE CONTINUING OPERATIONS. NO ALARM CO. WAS
MONITORING THE SYSTEM. GE5, G.G.P.D., AND PUBLIC WORKS DEPT. ALL SECURED
AFTER COMPLETION. CAPT. EDNOFF