

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1506153  
Exposure Number: 00  
Multi-Agency IC#:   
Incident Date: 05/30/15  
Dispatch Time: 06:36:16  
Arrival Time: 06:43:32  
Controlled Time:   
Ending Time: 07:39:45  
First-In Company: GE5  
District: G2114  
Incident Type: Water problem, other  
Mutual Aid: None  
Method of Alarm: Telephone  
Type of Weather:   
Air Temperature: 61  
Address, CSZ: 11330 MARKON DR  
Census Tract:   
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Shut down system  
Actions Taken 2:   
Actions Taken 3:   
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 0  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 1  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury:   
Non-FS Fatal:

## PROPERTY &amp; STUDIES

Property Losses:   
Content Losses:   
Property Value:   
Contents Value:   
Insurance Co:   
Building Ins:   
Mixed Prop Use:   
Property Use: Manufacturing, processing  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved:  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin  
Heat Source:  
First Item:  
Confined to Object:  
Material Type:  
Factor Causing:  
Contributing Factors 1:  
Contributing Factors 2:  
Human Factor Cont 1:  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved:  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status:  
# St Above Grnd:  
# St Below Grnd:

## INCIDENT REPORT

-----

Main Floor Size:  
Fire Origin:  
Extent of Flame:  
Number of Stories Damaged By Flame  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys:  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors:  
Detector Type:  
Det. Power Supply:  
Det. Operation:  
Det. Effectiveness:  
Det. Failure Reason:

-----

## COMMENTS

-----

\*\*\*\*\* GE5 \*\*\*\*\*

SERVICE-INVESTIGATION GE5  
ENCOUNTERED A SPRINKLER ACTIVATION IN A FURNITURE WAREHOUSE/WOODSHOP DUE TO  
A POSSIBLE TABLESAW/EQUIPMENT FIRE OUT P.T.A. GE5 SHUT DOWN THE SPRINKLER  
SYSTEM AND SECURED THE PROPERTY AFTER MULTIPLE ATTEMPTS TO CONTACT THE  
BUSINESS OWNER BY G.G.P.D. AND GE5 FAILED. (PHONE WAS NOT ANSWERED). ADJACENT  
BUSINESS WAS ADVISED TO NOTIFY THE SPRINKLER CO. TO RESPOND TO PUT THE  
SYSTEM BACK IN SERVICE BEFORE CONTINUING OPERATIONS. NO ALARM CO. WAS  
MONITORING THE SYSTEM. GE5, G.G.P.D., AND PUBLIC WORKS DEPT. ALL SECURED  
AFTER COMPLETION. CAPT. EDNOFF