

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1506153
Exposure Number: 00
Multi-Agency IC#:
Incident Date: 05/30/15
Dispatch Time: 06:36:16
Arrival Time: 06:43:32
Controlled Time:
Ending Time: 07:39:45
First-In Company: GE5
District: G2114
Incident Type: Water problem, other
Mutual Aid: None
Method of Alarm: Telephone
Type of Weather:
Air Temperature: 61
Address, CSZ: 11330 MARKON DR
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Shut down system
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 1
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury:
Non-FS Fatal:

PROPERTY & STUDIES

Property Losses:
Content Losses:
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Manufacturing, processing
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

COMMENTS

***** GE5 *****

SERVICE-INVESTIGATION GE5
ENCOUNTERED A SPRINKLER ACTIVATION IN A FURNITURE WAREHOUSE/WOODSHOP DUE TO
A POSSIBLE TABLESAW/EQUIPMENT FIRE OUT P.T.A. GE5 SHUT DOWN THE SPRINKLER
SYSTEM AND SECURED THE PROPERTY AFTER MULTIPLE ATTEMPTS TO CONTACT THE
BUSINESS OWNER BY G.G.P.D. AND GE5 FAILED. (PHONE WAS NOT ANSWERED). ADJACENT
BUSINESS WAS ADVISED TO NOTIFY THE SPRINKLER CO. TO RESPOND TO PUT THE
SYSTEM BACK IN SERVICE BEFORE CONTINUING OPERATIONS. NO ALARM CO. WAS
MONITORING THE SYSTEM. GE5, G.G.P.D., AND PUBLIC WORKS DEPT. ALL SECURED
AFTER COMPLETION. CAPT. EDNOFF