INCIDENT REPORT

_____ INCIDENT ______ Fire Department:
Incident Number:
Exposure Number:
Multi-Agency IC#:
Dispatch Time:
O3:11:53
Arrival Time:
O3:23:00 Controlled Time: Ending Time: 03:28:09 05:01:51 First-In Company: GE4 District G2313 Fires in structures other than in a building None Incident Type: Mutual Aid: Method of Alarm: E911 Type of Weather: Air Temperature 69 Address, CSZ: 6682 PICKETT AV Census Tract: Fire Haz Sev Zone: Medium _______ RESOURCES & CASUALTIES ______ Actions Taken 1: Extinguishment by fire service personnel Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: 0 #Apparatus Resp Med: 1
#Apparatus Resp Oth: 3 #Apparatus Resp Trk: 1 1 Fire Svs Fatal: 0 Non-FS Injury: 0 Non-FS Fatal: PROPERTY & STUDIES ______ Property Losses: \$10,000 \$2,500 Content Losses: Property Value: Contents Value: Insurance Co: Building Ins: Mixed Prop Use: Property Use: 1 or 2 family dwelling

Detector

INCIDENT REPORT

Hazmat	Re	: ⊥:
Critica	1	Inc:
Special	S	Studies:

None

EMERGENCY MEDICAL SERVICE

Number of Patients:

Billing Care:

Status:

Transported to:

Patients Trans - Fire:

Patients Trans - Amb:

COMMENTS

***** GE4 *****

STRUCTURE FIRE RESIDENTIAL

GE4 GE5 CE65 CT64 AND GB1 RESPONDED TO SINGLE STORY RESIDENTIAL FOR SMOKE COMING FROM GARAGE. GE5 INITIATED FIRE ATACK AND PRIMARY SEARCH. GE4 ASSUMED LAMPLIGHTER COMMAND, SECURED WATER SUPPLY AND ASSISTED GE5 WITH FIRE ATTACK. CE65 ASSIGNED BACK UP FIRE ATTACK AND TO CHECK EXTENSION. CT64 VENT GROUP AND FORCED ENTRY TO GARAGE. PROPERTY OWNER (IRA BUSHINSKY 714 658 2338) STATES HE HEARD A LOUD POP AND GOT UP FROM BED TO INVESTIGATE. SMOKE FOUND IN GARAGE AND HOUSE EVACUATED. FIRE LOCALIZED TO GARAGE AREA WITH NO EXTENSION TO HOUSE. UPON INVESTIGATION FIRE APPEARS TO BE ACCIDENTAL IN NATURE AND TO HAVE STARTED IN THE SOUTH WEST CORNER OF GARAGE IN AREA OF OF MULTIPLE WIRES BEING CONNECTED TO OUTLET. FOUR BREAKERS FOUND TRIPPED AT PANEL SERVICING KITCHEN BEDROOM WASHER DRYER AREAS.ARSON INVESTIGATOR JACOBS ON SCENE INVESTIGATING. INVOLVED AREA SALVAGED AND OVERHAULED. AREA SCANNED VIA THERMAL IMAGER UPON CLEAR TIME WITH NO HEAT SINATURES FOUND. RELEASE AND ASSUMPTION OF REAL PROPERTY AFETR EMERGENCY RESPONSE SIGNED BY HOMEOWNER. PROPERTY RELEASED BACK TO OWNER.

CAPTAIN WALDSCHMIDT