

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1510341
Exposure Number: 00
Multi-Agency IC#: 15-090903 00262265
Incident Date: 09/09/15
Dispatch Time: 15:31:11
Arrival Time: 15:35:28
Controlled Time: 15:46:44
Ending Time: 19:38:00
First-In Company: GE2
District: G2317
Incident Type: Building fire
Mutual Aid: Mutual aid received
Method of Alarm: W911
Type of Weather:
Air Temperature: 100
Address, CSZ: 12161 MAGNOLIA ST
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Fire control or extinguishment, other
Actions Taken 2: Salvage & overhaul
Actions Taken 3: Extinguishment by fire service personnel
#Apparatus Resp Engine: 4
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 8
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 1
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$80,000
Content Losses: \$40,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Residential, other
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin: Undetermined
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Cause under investigation
Contributing Factors 1: Fire spread or control, other
Contributing Factors 2:
Human Factor Cont 1: Asleep
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Undetermined
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Other power source
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 2

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 800
Extent of Flame: Undetermined
Number of Stories Damage: Confined to floor of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Present
Detector Type: Smoke
Det. Power Supply: Plug in
Det. Operation: Detector operated
Det. Effectiveness: Alerted occupants, occupants responded
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:
Int Observations 3:
Lab Used 1:
Lab Used 2:
Lab used 3:

ARSON COMMENTS

BASED UPON FIRE SCENE EXAMINATION AND WITNESS STATEMENTS, IT IS THE CONCLUSION OF THIS FIRE INVESTIGATOR THAT THE FIRE ORIGINATED AT THE BOTTOM OF THE EXTERIOR STAIRCASE, AND THE MOST PROBABLE CAUSE OF IGNITION WAS IMPROPER DISPOSAL OF SMOKING MATERIAL. THIS FIRE IS RULED AS ACCIDENTAL.

THIS INVESTIGATION IS CLOSED

CAPTAIN STROHM

PATIENT REPORT

Name Unknown (OC-MEDS Import)
DOB, Age, Sex 36 Female
Address, CSZ:
Country:
Telephone:
Driver's Lic#:
SS Number:
Employer:
Emp Phone:
Relative:
Rel Phone:
Insurance:
Police #:
Billing Care:
Status:
Transported To:
Transported By:
ALS Intervention:
Escorted:
Procedures Used 1: No treatment
Procedures Used 2:
Procedures Used 3:
Arrived Date:
Transport Date:
Assessment: Trauma
Other Factors:
Human Factors 1:
Human Factors 2:
Human Factors 3:
Cause of Injury: Fall

INCIDENT REPORT

Body Site of Injury 1:
Body Site of Injury 2:
Body Site of Injury:
Safety Equipment:
Cardiac Arrest:
CA Prearrival:
CA Init Rhythm:
Initial Care Level:
Highest Care Level:
Patient Status:
Pulse on Transfer:
Disposition:

COMMENTS

***** GE2 *****

STRUCTURE FIRE- 2 STORY APARTMENT BUILDING GE2,GE5,CE46,CT64,GT1,
GE1,GM1,GB1

GE2 RESPONDED TO 12161 MAGNOLIA ON A STRUCTURE FIRE. GE2 STATED A 2 STORY APARTMENT BUILDING WITH HEAVY SMOKE SHOWING FROM THE SECOND FLOOR. GE2 WENT IN THE ATTACK MODE AND INITIATED A PRIMARY SEARCH. GE2 ALSO REQUESTED THE SECOND IN UNIT TO COMPLETE THE WATER SUPPLY. GE2 THEN REQUESTED A WORKING FIRE ASSIGNMENT THROUGH METRO-NET. GE2 MADE ENTRY TO THE SECOND FLOOR AND NOTICED THE EXTERIOR STAIRS WERE EXTREMELY BURNED. GE2 STARTED TO INITIATE A PRIMARY SEARCH WHILE LOCATING THE SEAT OF THE FIRE. GE2 WAS NAMED FIRE ATTACK AND WAS GIVEN THE BALANCE OF GE5 CREW TO HELP OUT IN FIRE ATTACK. GT1 WAS VENT GROUP AND PERFORMED VERTICAL VENTILATION. CE46 ALSO BACKED UP FIRE ATTACK. FIRE ATTACKED STATED THAT THE FIRE WAS KNOCKED DOWN AND THE PRIMARY SEARCH WAS COMPLETE. FIRE ATTACK ALSO CHECKED FOR EXTENSION AND FOUND FIRE IN THE STAIRWELL. CREWS THEN STARTED TO BREAK AWAY THE STUCCO AND NOTICED THE STAIRWELL WAS BADLY DAMAGED BY FIRE. THERE WERE LATER REPORTS THAT THERE WAS 1 VICTUM IN THE APARTMENT WHO JUMPED FROM A SECOND STORY WINDOW ONTO A MATTRESS TO ESCAPE THE FIRE. THE PATIENT WAS THEN CHECKED OUT BY GE5 PARAMEDICS BUT THE PATIENT DECIDED TO REFUSE TREATMENT AND SIGNED AMA. GE2, GT1 PERFORMED SALVAGE AND HELPED OUT THE TENANTS WITH GATHERING THEIR BELONGINGS. RED CROSS WAS ALSO REQUESTED BY THE IC FOR MULTIPLE PEOPLE THAT NEEDED ASSISTANCE. GE2 AND GT1 THEN PERFORMED OVERHAUL THAT INCLUDED THE USE OF FOAM. GE2 MADE CONTACT WITH THE PROPERTY OWNER ON SCENE AND FILLED OUT A RELEASE & ASSUMPTION OF RISK OF REAL PROPERTY FORM. GE2 CAPTAIN EXPLAINED THE FORM AND HAD THE OWNER SIGN AND DATE IT. GE2 THEN RELEASED THE PROPERTY BACK TO THE PROPERTY OWNER. GE2 WAS THEN COMPLETE.

CAPTAIN PARDOEN