

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1507680
Exposure Number: 00
Multi-Agency IC#: 15-067128
Incident Date: 07/06/15
Dispatch Time: 22:46:20
Arrival Time: 22:51:27
Controlled Time: 23:02:39
Ending Time: 00:59:35
First-In Company: GE5
District: G2516
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 65
Address, CSZ: 13122 JEFFERSON ST APT B
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 4
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$10,000
Content Losses: \$2,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Multifamily dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Roof surface: exterior
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Misuse of material or product, other
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 2

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 1000
Extent of Flame: Roof surface: exterior
Number of Stories Damage: Confined to room of origin
Minor: 1
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Present
Detector Type: Smoke
Det. Power Supply: Battery only
Det. Operation: Detector operated
Det. Effectiveness: Undetermined
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factos 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:
Int Observations 3:
Lab Used 1:
Lab Used 2:
Lab used 3:

COMMENTS

***** GE5 *****

STRUCTURE FIRE RESIDENTIAL

GE5 RESPONDED WITH GB1, CE64, CT64 AND GE2 TO AN APT BUILDING FOR A STRUCTURE FIRE TO ARRIVE TO FIND OCCUPANTS OUTSIDE PUTTING WATER ON A ROOF FIRE. GE5 PULLED HOSELINES INTO THE APT AND CONDUCTED A PRIMARY SEARCH AND CHECKED FOR EXTENSION INTO THE HOUSE. GE5 FOUND A SMALL AMOUNT OF FIRE IN THE ATTIC ON THE SECOND FLOOR WHERE THE ROOF FIRE HAD BURNED THROUGH AND CAUGHT THE INSULATION ON FIRE. GE5 EXTINGUISHED THE FIRE FROM INSIDE THE HOUSE WHILE CT64 CUT AWAY THE ROOFING MATERIAL THAT WAS INVOLVED FROM THE ROOF. GE2 ASSUMED COMMAND UNTIL GB1 WAS ON SCENE WHEN THEY WERE THEN ASSIGNED TO CHECK THE NEXT DOOR EXPOSURE. CE64 ASSISTED GE5 IN THE MAIN UNIT WITH EXTINGUISHMENT AND OVERHAUL. FIRE WAS EXTINGUISHED AND ALL INVOLVED ROOFING MATERIAL WAS REMOVED. CAPT WILKINS WAS DISPATCHED ON GE1 AS AN INVESTIGATOR AND PERFORMED A FIRE INVESTIGATION ON THE FIRE, REPORT WILL BE ATTACHED. GE5 COMPLETED THE OVERHAUL PROCESS AND RELEASED THE PROPERTY TO THE BUILDING OWNER, ADVISING HIM THAT UTILITIES HAVE BEEN SHUT DOWN. GE5 CLEARED THE CALL.

CAPT MAULE