

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1512377
Exposure Number: 00
Multi-Agency IC#: 15-110155
Incident Date: 10/29/15
Dispatch Time: 17:45:43
Arrival Time: 17:51:04
Controlled Time: 17:55:11
Ending Time: 19:08:05
First-In Company: GE4
District: G2410
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 87
Address, CSZ: 5401 PARK AV
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 3
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$5,000
Content Losses: \$3,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

EMERGENCY MEDICAL SERVICE

Number of Patients:
Billing Care:
Status:
Transported to:
Patients Trans - Fire:
Patients Trans - Amb:

COMMENTS

***** GE4 *****

FIRE STRUCTURE FIRE CAPT RUHMAN

GE4 GB1 GE5 CE65 CT64 RESPONDED TO A RESIDENCE FOR A STRUCTURE FIRE. GE4 FOUND SINGLE STORY HOUSE WITH LIGHT SMOKE SHOWING FROM THE EVES. GE4 WENT INTO ATTACK MODE AND INITIATED A PRIMARY SEARCH. A PRECONNECT LINE WAS USED AND WE WERE ABLE TO SECURE OUR OWN WATER. FLAMES WERE FOUND IN THE CORNER OF THE OFFICE ADJACENT TO THE FRONT DOOR. THE FIRE WAS IMMEDIATELY EXTINGUISHED AND NO EXTENSION WAS FOUND. BOTH PRIMARY AND SECONDARY WERE CLEAR. OCCUPANT ANTHONY HILL STATED HE WAS AT HOME AND HAD PLUGGED A BRAND NEW LAPTOP IN TO CHARGE ON THE DESK NEAR WHERE THE FIRE STARTED. HE THEN LEFT THE RESIDENCE FOR APPROX 15 MINUTES AND WHEN HE ARRIVED BACK HOME HE FOUND SMOKE IN THE RESIDENCE WITH DETECTORS SOUNDING. HE IMMEDIATELY EVACUATED THE RESIDENCE. THE LAPTOP WAS MELTED AND CHARRING WAS SEEN ON THE TOP OF THE DESK AND THE WALL BEHIND AND LEFT OF THE DESK WHERE A BURNED BOOKCASE ONCE STOOD FROM THE FLOOR TO CEILING. THERE WAS ALSO AN OUTLET WITH CONSIDERABLE CHARRING NOTED. THE ELECTRICAL PANNEL HAD ONE BREAKER THAT WAS TRIPPED AND WAS LEFT SHUT OFF ALONG WITH THE MAIN THAT FD PERSONNEL ACCESSED. AFTER INVESTIGATION ON SCENE IT APPEARS TO BE ACCIDENTAL IN NATURE AND THE CAUSE IS UNDETERMINED.