INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department Incident Number: G1513464

Exposure Number: 00

Multi-Agency IC#:

Incident Date: 11/26/15 Dispatch Time: 17:38:20 Arrival Time: 17:42:38 17:47:05 Controlled Time: Ending Time: 18:22:24 First-In Company: GE 6

District G2323

Incident Type: Cooking fire, confined to container

Mutual Aid: None

Method of Alarm: Telephone

Type of Weather:

Air Temperature 65

Address, CSZ: 11732 JOHN AV

Census Tract:

Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

______ Actions Taken 1: Extinguishment by fire service personnel Actions Taken 2: Search

Actions Taken 3:

#Apparatus Resp Engine: 0 #Apparatus Resp Trk: 1 #Apparatus Resp Med: 1
#Apparatus Resp Oth: 4 Fire Svs Injury: 0 Fire Svs Fatal: 0 Non-FS Injury: 0 Non-FS Fatal:

PROPERTY & STUDIES

Property Losses: \$2,000

\$2,000

Content Losses: Property Value:

Contents Value: Insurance Co: Building Ins: Mixed Prop Use:

1 or 2 family dwelling
Detector alerted occupy Property Use: Detector Detector alerted occupants

INCIDENT REPORT

Hazmat Rel: None Critical Inc:

Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:

Bldgs. Involved:

Acres Burned:

On-Site Mat/Stor:

Area of Origin

Cooking area, kitchen

Heat Source:

Hot or smoldering object, other

First Item:

Undetermined

Confined to Object:

Material Type:

Factor Causing:

Unintentional

Contributing Factors 1: Factors contributing to ignition, other

Contributing Factors 2:

Human Factor Cont 1: None

Human Factor Cont 2:

Human Factor Cont 3:

Age Sex

Equip Involved:

Oven, rotisserie

Equip Brand:

Equip Model:

Equip Serial Number:

Equip Year:

Equip Power Source: Gas fuels, other

Equip Portability:

Stationary

Mobile Prop Inv:

None

Mobile Prop Type:

Mobile Prop Make:

Mobile Prop Model:

Mobile Prop Year:

Mobile Prop Lic. Plate:

Mobile Prop Lic. State:

Mobile Prop VIN Number: Mobile Prop Stolen?:

Suppression Factors:

COMMENTS

**** GE6 ****

INCIDENT REPORT

GE6 RESPONDED TO THE ABOVE ADDRESS FOR A STRUCTURE FIRE. UPON ARRIVAL, FOUND LIGHT SMOKE SHOWING FROM THE FRONT DOOR. GE6 INVESTIGATED, FOUND AN ACTIVE FIRE IN THE KITCHEN. E6 PULLED A HOSE LINE AND EXTINGUISHED THE FIRE. FIRE WAS CONFINED TO THE OVEN AREA. MINOR SMOKE AND WATER DAMAGE TO THE KITCHEN. NO INJURIES TO THE OCCUPANTS OR FIREFIGHTERS.

FIRE WAS CAUSED BY OVEN BEING IN CLEANING MODE WITH GREASE LEFT INSIDE THE OVEN. OWNER WAS ADVISE THAT THE GAS WAS SHUT DOWN TO THE PROPERTY AND THEY NEED TO CALL THE GAS COMPANY BEFORE TURNING IT BACK ON. OWNER SIGNED PROPERTY RELEASE.

CAPTAIN TRENHOLM