

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1513743  
Exposure Number: 00  
Multi-Agency IC#: 15-123192 A1536911  
Incident Date: 12/04/15  
Dispatch Time: 09:34:14  
Arrival Time: 09:38:16  
Controlled Time: 10:00:59  
Ending Time: 10:58:23  
First-In Company: GE7  
District: G2620  
Incident Type: Cooking fire, confined to container  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:  
Air Temperature: 57  
Address, CSZ: 13838 BROOKHURST ST  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Salvage & overhaul  
Actions Taken 3:  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 7  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$5,000  
Content Losses: \$25,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: Food and beverage sales, grocery store  
Detector: Undetermined

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved:  
Acres Burned:  
On-Site Mat/Stor: Baked goods  
Area of Origin: Service facilities, other  
Heat Source: Radiated, conducted heat from operating  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Failure of equipment or heat source  
Contributing Factors 1: Worn out  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: Kitchen & cooking equipment, other  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source: Electrical line voltage (> 50 volts)  
Equip Portability: Stationary  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status: Enclosed building  
# St Above Grnd: Occupied and operating  
# St Below Grnd: 1

## INCIDENT REPORT

-----

Main Floor Size: 0  
Fire Origin: 1500  
Extent of Flame: Service facilities, other  
Number of Stories Damage: Confined to building of origin  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys: Present  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors: Present  
Detector Type: Undetermined  
Det. Power Supply: Undetermined  
Det. Operation: Undetermined  
Det. Effectiveness:  
Det. Failure Reason:

-----

## COMMENTS

-----

\*\*\*\*\* GE7 \*\*\*\*\*

## CONTENTS FIRE

GE7 ARRIVED TO FIND FIRE EMITTING FROM A VENT PIPE ON THE ROOF OF THE REPORTED ADDRESS. GE7 ENTERED THE BUSINESS AND FOUND MODERATE SMOKE CONDITIONS AND KITCHEN EQUIPMENT ON FIRE. GE7 EXTINGUISHED THE FIRE AND CHECKED FOR EXTENSION. OVERHAUL WAS PERFORMED AND THE OWNER WAS ADVISED OF THE DAMAGES AND SIGNED A PROPERTY RELEASE.

CAPTAIN  
M.WEISS