INCIDENT REPORT

INCIDENT
arden Grove Fire Department 1600973 0 1602819 1/26/16 6:13:40 6:18:26 6:29:13 8:26:08 E2 2420 uilding fire one 911 8 2561 KENSINGTON LN edium
RESOURCES & CASUALTIES
xtinguishment by fire service personnel alvage & overhaul 0 1 0 8
PROPERTY & STUDIES
\$25,000 \$15,000 arking garage, (detached residential ga

Detector

INCIDENT REPORT

Hazmat Rel:

None

Undetermined

Undetermined

Unintentional

Undetermined

Electrical, other

Portable

None

Critical Inc: Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:

Bldgs. Involved:

Acres Burned:

On-Site Mat/Stor: On-site materials, other
Area of Origin Vehicle storage area; garage, carport
Heat Source: Undetermined

Heat Source:

First Item:

Confined to Object:

Material Type:

Factor Causing:

Contributing Factors 1: Undetermined Contributing Factors 2:

Human Factor Cont 1: Human Factor Cont 2:

Human Factor Cont 3:

Age Sex

Equip Involved:

Equip Brand:

Equip Model:

Equip Serial Number:

Equip Year:

Equip Power Source:

Equip Portability:

Mobile Prop Inv: Mobile Prop Type:

Mobile Prop Make: Mobile Prop Model:

Mobile Prop Year:

Mobile Prop Lic. Plate: Mobile Prop Lic. State:

Mobile Prop VIN Number: Mobile Prop Stolen?:

Suppression Factors:

STRUCTURE FIRE

Type:

Status:

Enclosed building

St Above Grnd:

Other

St Below Grnd:

1

INCIDENT REPORT

Main Floor Size:

0

Fire Origin: 150 Extent of Flame: Vehicle storage area; garage, carport

Number of Stories DamageConfined to room of origin

Minor: Sign: Heavy;

Extreme:

Auto Ext Sys:

None Present

AES Type:

AES Operation:

Sprinkler Heads: AES Failure Reason:

Detectors:

Not present

Detector Type:

Det. Power Supply:

Det. Operation:

Det. Effectiveness:

Det. Failure Reason:

COMMENTS

**** GE2 ****

STRUCTURE FIRE-2 STORY APARTMENT WITH DETACHED GARAGE

GE2 RESPONDED TO 12561 KENSINGTON LN FOR A REPORT OF A STRUCTURE FIRE. GE2 CAME ON SCENE FIRST AND STATED THAT THERE WAS A FULLY INVOLVED DETACHED GARAGE FIRE AND A FULLY INVOLVED CAR FIRE WITH THE TWO STORY APARTMENT BEING THE PRIMARY EXPOSURE. GE2 WENT INTO THE ATTACK MODE AND HAD THE SECOND ENGINE COMPLETE OUR WATER SUPPLY AND TAKE COMMAND. THE FIRE WAS KNOCKED DOWN WITH IN 15 MINUTES. GE1 CHECKED THE APARTMENTS AND STATED THAT THEY WERE CLEAR. GE2, GE1 AND GE7 CHECKED THE AJACENT GARAGES FOR EXTENSION. GE2 FOUND THAT THERE WAS SLIGHT EXTENSION TO THE GARAGE DIRECTLY NEXT TO THE INVOLVED GARAGE. GT1 STARTED VENTILATION TO RELIEVE THE EXCESS HEAT AND SMOKE. GT1 ALSO STARTED TO CUT INTO THE FACIA BOARD AND LIFTED THE ROOF FLASHING DUE TO SMOULDERING HOT SPOTS. ONCE THE FIRE WAS COMPLETELY KNOCKED DOWN, GE1 CAPTAIN WILKINS STARTED HIS FIRE INVESTIGATION. GE2 THEN STARTED OVERHAUL ON THE GARAGE AND PLACED ALL ITEMS IN THE ALLEY NEXT TO THE GARAGE. GE2 THEN USED CLASS A/B FOAM TO COVER THE ENTIRE GARAGE TO COMPLETE THE OVERHAUL PROCESS. GE2 MET WITH THE PROPERTY OWNER AND HIM SIGN A CITY OF GARDEN GROVE RELEASE & ASSUMPTION OF RISK OF REAL PROPERTY AFTER EMERGENCY RESPONSE FORM. GE2 STATED THE CONCERNS ON THE FORM AND HAD THE OWNER SIGN IT. FIRE IS STILL UNDER FURTHER INVESTIGATION AND WILL BE ATTACHED TO THIS REPORT FROM CAPTAIN WILKINS WHO IS THE LEVEL 1 ARSON INVESTIGATOR.

CAPTAIN PARDOEN