

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1601496  
Exposure Number: 00  
Multi-Agency IC#: A1604332 16-014913  
Incident Date: 02/08/16  
Dispatch Time: 18:10:24  
Arrival Time: 18:16:07  
Controlled Time: 18:30:21  
Ending Time: 21:03:27  
First-In Company: GE2  
District: G2419  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: Telephone  
Type of Weather:  
Air Temperature: 81  
Address, CSZ: 9542 LAMPSON AV  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Ventilate  
Actions Taken 3: Salvage & overhaul  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 5  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$150,000  
Content Losses: \$40,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: 1 or 2 family dwelling  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## EMERGENCY MEDICAL SERVICE

Number of Patients:  
Billing Care:  
Status:  
Transported to:  
# Patients Trans - Fire:  
# Patients Trans - Amb:

## COMMENTS

\*\*\*\*\* GE2 \*\*\*\*\*

FIRE STRUCTURE FIRE RESIDENTIAL

GE2 ARRIVED ON SCENE OF A ONE STORY SINGLE FAMILY RESIDENCE TO FIND AN ATTACHED GARAGE WELL INVOLVED IN FIRE WITH ONE AUTO IN THE GARAGE. GE2 IN ATTACK MODE WITH NEXT IN TAKING COMMAND AND COMPLETING OUR WATER SUPPLY. GE2 INITIAL ATTACK WITH 2 150' - 1 3/4" PRECONNECTED HOSELINES ON THE GARAGE FIRE. GE2 LEFT ONE FIREFIGHTER FIGHTING THE GARAGE FIRE FROM THE EXTERIOR AND THE OTHER FIREFIGHTER BROUGHT A HANDLINE INTO THE INTERIOR TO COMPLETE A PRIMARY SEARCH AND CHECK FOR EXTENSION. GE2 WITH PRIMARY ALL CLEAR. GE2 FOUND EXTENSION IN THE ATTIC SPACE BETWEEN THE FIREWALL OF THE GARAGE AND KITCHEN AREA DUE TO A BREACH IN THE FIREWALL AT THE SOUTHWEST CORNER OF THE GARAGE. THE FIRE EXTENSION WAS QUICKLY CONTROLLED. WIRES WERE DOWN IN THE REAR YARD OF THE PROPERTY DUE TO FIRE IMPINGMENT TO THE DROP LINE AT THE DRIP LOOP. EDISON RESPONDED TO THE SCENE. GE2 WITH A SECONDARY SEARCH ALL CLEAR. GT1 ASSIGNED VENT GROUP AND CUT THREE HOLES; TWO OVER THE GARAGE AND ONE OVER THE LIVING AREA. FIRE WAS UNDER CONTROL WITHIN 15-20 MINUTES. GT1 WITH SALVAGE IN THE LIVING ROOM AREA. LEVEL 1 INVESTIGATOR, CAPTAIN ABRAHAMSON, COMPLETED THE FIRE INVESTIGATION. OVERHAUL COMPLETED AND FOAM USED IN INTERIOR ATTIC SPACE AND GARAGE. PROPERTY OWNERS STATED THERE WAS NO NEED FOR RED CROSS. PROPERTY OWNER SIGNED AND WAS GIVEN A COPY OF THE RELEASE FORM. GE2 COMPLETED.

CAPTAIN BRENEMAN