

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1511544
Exposure Number: 00
Multi-Agency IC#: 15-101758
Incident Date: 10/07/15
Dispatch Time: 19:11:52
Arrival Time: 19:17:19
Controlled Time: 19:31:28
Ending Time: 21:39:47
First-In Company: GE7
District: G2618
Incident Type: Fires in structures other than in a building
Mutual Aid: None
Method of Alarm: W911
Type of Weather:
Air Temperature: 78
Address, CSZ: 13742 MAGNOLIA ST
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 2
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$20,000
Content Losses: \$10,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Bedroom - < 5 persons; included are jail or prison
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Undetermined
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Other power source
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Structure type, other
St Above Grnd:
St Below Grnd:

INCIDENT REPORT

Main Floor Size:
Fire Origin:
Extent of Flame: Bedroom -- < 5 persons; included are jail
Number of Stories Damaged By Flame
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys:
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors:
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE7 *****

STRUCTURE FIRE RESIDENTIAL

GE7 RESPONDED WITH GB1, CE66, CE64, CT64, GT1 AND GM1 TO A HOUSE WITH A BEDROOM FIRE. CE66 ARRIVED AND ESTABLISHED COMMAND, AND GE7 WAS ASSIGNED INTERIOR WITH CE66 CREW AS WELL AS GM1. GE7 MADE A QUICK ATTACK ON THE BEDROOM FIRE AND CONDUCTED A PRIMARY AND SECONDARY SEARCH OF THE HOUSE. THE FIRE WAS EXTINGUISHED AND NO OCCUPANTS WERE INSIDE. FIRE WAS OVERHAULED BY GT1 AND GE7, AND RED CROSS WAS DISPATCHED FOR THE FAMILY. GE7 AND GT1 COULD NOT DETERMINE THE EXACT CAUSE OF THE FIRE DUE TO EXTENSIVE DAMAGE OF THE FIRE ROOM. A PROPERTY RELEASE WAS FILLED OUT WITH THE PROPERTY OWNER, AND ALL CREWS WERE CLEAR OF THE CALL.

RP WENDY NGUYEN

CAPT MAULE