

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1604042  
Exposure Number: 00  
Multi-Agency IC#: A1611323 16-039043  
Incident Date: 04/12/16  
Dispatch Time: 06:02:26  
Arrival Time: 06:08:36  
Controlled Time: 06:20:00  
Ending Time: 08:25:07  
First-In Company: GE2  
District: G2117  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:  
Air Temperature: 54  
Address, CSZ: 11062 MAC MURRAY ST  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2:  
Actions Taken 3:  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 3  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$50,000  
Content Losses: \$20,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: 1 or 2 family dwelling  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved: 1  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin Bedroom - < 5 persons; included are jail or prison  
Heat Source: Undetermined  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Unintentional  
Contributing Factors 1: Undetermined  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: None  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status: Enclosed building  
# St Above Grnd: Occupied and operating  
# St Below Grnd: 1

## INCIDENT REPORT

-----

Main Floor Size: 0  
Fire Origin: 1700  
Extent of Flame: Bedroom - < 5 persons; included are jail  
Number of Stories Damage: Confined to room of origin  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys: None Present  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors: Unknown  
Detector Type:  
Det. Power Supply:  
Det. Operation:  
Det. Effectiveness:  
Det. Failure Reason:

-----

## COMMENTS

-----

\*\*\*\*\* GE2 \*\*\*\*\*

## FIRE

GE2 WAS DISPATCHED TO A STRUCTURE FIRE. GE2 ARRIVED AND FOUND A SINGLE FAMILY HOUSE WITH SMOKE AND FIRE SHOWING FROM THE FRONT. GE2 ASSUMED FIRE ATTACK AND EXTINGUISHED THE FIRE. GE2 ASSISTED WITH OVERHAUL. GE2 REVIEWED THE PROPERTY RELEASE FORM WITH THE PROPERTY OWNER. SCENE WAS RELEASED BACK TO THE HOME OWNER. FIRE INVESTIGATION TO BE FOLLOWED UP BY GGFD INVESTIGATOR MIKE JACOBS.

CAPTAIN STROHM