

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1604919  
Exposure Number: 00  
Multi-Agency IC#: A1613621 00151777 01605041 16-047107  
Incident Date: 05/04/16  
Dispatch Time: 03:23:12  
Arrival Time: 03:28:29  
Controlled Time: 06:10:47  
Ending Time: 11:51:51  
First-In Company: GE2  
District: G2319  
Incident Type: Fire, other  
Mutual Aid: None  
Method of Alarm: Telephone  
Type of Weather:  
Air Temperature: 0  
Address, CSZ: WORLD BUFFET, 12125 BROOKHURST  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Fire control or extinguishment, other  
Actions Taken 2:  
Actions Taken 3:  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 14  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$1,500,000  
Content Losses: \$1,500,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: Food and beverage sales, grocery store  
Detector: Undetermined

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## EMERGENCY MEDICAL SERVICE

Number of Patients:  
Billing Care:  
Status:  
Transported to:  
# Patients Trans - Fire:  
# Patients Trans - Amb:

## COMMENTS

\*\*\*\*\* GE2 \*\*\*\*\*

## STRUCTURE FIRE-SINGLE STORY COMMERCIAL BUILDING

GE2 RESPONDED TO 12093 BROOKHURST ST #E FOR A REPORT OF A STRUCTURE FIRE AT 03:23 HOURS. EN ROUTE NOTES FROM METRONET INDICATED THE LOCATION WAS POSSIBLY AT EL POLLO LOCO RESTAURANT. GE2 CONTINUED IN AND APPROCHED THE INTERSECTION OF BROOKHURST ST/CHAPMAN AVE AND NOTICED A MEDIUM AMOUNT OF SMOKE IN THE AREA. GE2 CONTINUED SOUTH ON BROOKHURST ST TO GET A 360 VIEW OF THE BUILDING. GE2 INITIAL SIZE UP WAS GE2 ONSCENE WITH FOUR, SINGLE STORY COMMERCIAL BUILDING WHICH WAS THE CLAWS RESTAURANT, MEDIUM AMOUNT OF SMOKE SHOWING, GE2 WILL BE INVESTIGATING, CONTINUE THE ASSIGNMENT AND STAND BY FOR A SECONDARY SIZE UP. UPON COMPLETING THE 360 OF THE STRUCTURE GE2 NOTICED MEDIUM TO HEAVE SMOKE SHOWING FROM THE ROOF AND THE FRONT DOOR TO THE RESTAURANT. GE2 WENT INTO THE ATTACK MODE AND INITIATED A PRIMARY SEARCH. GE2 HAD SECOND UNIT ONSCENE COMPLETE THE WATER SUPPLY, TAKE COMMAND AND THEN GE2 UPGRADED TO A WORKING FIRE ASSIGNMENT. GE2 FORCED ENTRY INTO THE FRONT OF THE RESTAURANT AND INITIATED A PRIMARY SEARCH. GB1 ESTABLISHED COMMAND AND MADE GE2 FIRE ATTACK AND ASSIGNED GE6 TO BACK UP FIRE ATTACK. ABOUT APPROXIMANTLY 5 MINUTES OF BEING INSIDE GE2 RECEIVED EMERGENCY PRIORITY TRAFFIC. GB1 RELAYED THAT FIRE WAS THROUGH THR ROOF AND WE HAD APPROX TWO MINUTES TO EXIT THE BUILDING. UPON COPYING THE RADIO TRAFFIC GE2 EXPERIENCED CEILING COLLAPSE INSIDE AND GE2 TOLD GE6 AND GE2 CREW TO EXIT THE BUILDING IMMEDIATELY. ONCE EVERYONE WAS OUTSIDE GE2 RELAYED TO GB1 THAT ALL PERSONEL WAS ACCOUNTED FOR. GB1 MAKE THE INCIDENT A DEFENSIVE FIRE AND ASSIGNED GE2 TO ASSUME DIVISION ALPHA WHICH WAS THE INITIAL TACTICAL FRONT OF THE BUILDING. GE2 STARTED DEPLOYING MASTER STREAMS TO THE ALPHA SIDE OF THE BUILDING OUTSIDE OF THE COLLAPSE ZONE. DIVISION ALPHA RELAYED TO COMMAND THAT FIRE WAS EXTENDING TO THE FASADE OUTSIDE OF THE STRUCTURE. AB2 ASSUMED DIVISION ALPHA AFTER TRAINING CAPTAIN TRUHILL TOOK OVER SAFETY. GE2 CONTINUED TO PLACE MASTER STREAMS TO THE ALPHA SIDE OF THE STRUCTURE WITH 2 ½ HANDLINES AND A GROUND MONITOR. GE2 ALSO SUPPLIED CT64 FOR A LADDERPIPE OPERATION TO THE ALPHA BRAVO CORNER. UNITS WERE PLACED ON THE ALPHA, BRAVO, CHARLIE AND DELTA SIDES OF THE BUILDING WITH MASTER STREAMS IN PLACE ALONG

INCIDENT REPORT

---

WITH THREE TRUCK COMPANIES WITH LADDER PIPE OPERATIONS IN PLACE. PER COMMAND THE INCIDENT WENT TO FOUR ALARMS WITH NO REPORTED INJURIES. UNITS WERE STRATEGICLY SENT TO REHAB OVER THE COURSE OF THE INCIDENT. FIRE IS UNDER INVESTIGATION BY LEVEL 2 ARSON INVESTIGATORS CAPTAIN KUHLMAN AND CAPTAIN STROHM. AB2 AT APPROX 07:30 WAS CLEARED FROM THE INCIDENT AND GE2 ASSUMED DIVISION ALPHA FROM AB2. GB1 ORDERED HEAVY EQUIPMENT FROM THE CITY YARD WHICH WAS USED TO TEAR DOWN THE CHARLIE SIDE FASADE DUE TO IT COLLAPSING. DURING OVERHAUL GE3 SUPPLIED GT1 FOAM TO USE FROM AN ARIAL POSITION. AT AROUND 10:00 HRS GE2 WAS COMPLETE AND GE6 TOOK OVER IN THE OVERHAUL PROCESS. EARLY REPORTS INDICATED THAT 1.5 MILLION DOLLARS IN DAMAGE OCCURRED BUT THAT FIGURE AND THE CAUSE IS STILL UNDER INVESTIGATION BY GGFD ARSON INVESTIGATORS.

CAPTAIN PARDOEN