INCIDENT REPORT

	INCIDENT
	Garden Grove Fire Department G1604385 00 16-042289 04/20/16 19:20:53 19:24:59 19:31:51 22:13:08 GE3 GZ725 Building fire None Telephone 85 12562 MORNINGSIDE AV
	RESOURCES & CASUALTIES
Actions Taken 1: Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: #Apparatus Resp Med: #Apparatus Resp Med: #Apparatus Resp Oth: Fire Svs Injury: Fire Svs Fatal: Non-FS Injury:	Extinguishment by fire service personnel Investigate Salvage & overhaul 0 1 5 0 0 0 0
	PROPERTY & STUDIES
Property Losses: Content Losses: Property Value: Contents Value: Insurance Co: Building Ins: Mixed Prop Use:	\$200,000 \$20,000 Multifamily dwelling

INCIDENT REPORT

Hazmat Rel:	
-------------	--

None

Critical Inc: Special Studies:

COMMENTS

***** GE3 ****

STRUCTURE FIRE

RESPONDED ON A REPORTED STRUCTURE FIRE. UPON ARRIVAL FOUND A TWO STORY APARTMENT BUILDING WITH FIRE COMING FROM A FIRST STORY APARTMENT ON THE NORTH SIDE OF THE BUILDING AND FIRE EXTENDING TO THE EVES OF THE ROOF. GE3 ATTACKED THE FIRE WITH A PRECONNECTED HOSELINE AND ON BOARD WATER AND ADDITIONALLY DID A SEARCH. GROVE BATTALION ONE TOOK INCIDENT COMMAND.

UPON EXTINGUISHMENT OF THE FIRE AN INVESTIGATION WAS CONDUCTED TO DETERMINE CAUSE AND ORIGIN. BASED UPON THE FIRE SCENE EXAMINATION AND WITNESS STATEMENTS, IT IS THE CONCLUSION OF THIS FIRE INVESTIGATOR THAT THE FIRE ORIGINATED IN THE NORTH WEST BEDROOM, AND MORE SPECIFICALLY ALONG THE NORTH WALL OF THE BEDROOM. I BELIEVE THAT THE FIRE WAS STARTED BY AN UNSPECIFIED FAILURE OF AN ELECTRICAL COMPONENT THAT WAS PLUGGED INTO THE OUTLET ON THE NORTH WALL. THE STRUCTURES ELECTRICAL SYSTEM DID NOT CONTRIBUTE TO THIS FIRE. THE FIRE WAS RULED AS ACCIDENTAL IN NATURE. THE INVESTIGATION OF THIS FIRE IS CLOSED.

FOLLOWING THE INVESTIGATION OVERHAUL WAS PERFORMED AND PROPERTY WAS SECURED FOR THE RESIDENTS. A RELEASE OF REAL PROPERTY FOLLOWING AN EMERGENCY RESPONSE FORM WAS COMPLETED AND SIGNED BY PROPERTY OWNERS REPRESENTATIVE.

CAPTAIN JEFFREY LEE WILKINS