

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1203897
Exposure Number: 00
Multi-Agency IC#: A1210256 00096888
Incident Date: 05/01/12
Dispatch Time: 09:29:26
Arrival Time: 09:33:22
Controlled Time: 09:48:47
Ending Time: 12:19:25
First-In Company: GE1
District: G2422
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 64
Address, CSZ: 12561 WALNUT AV
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Salvage & overhaul
Actions Taken 3: Investigate
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 5
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$150,000
Content Losses: \$50,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Function areas, other
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Cause under investigation
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 800
Extent of Flame: Function areas, other
Number of Stories Damage: Confined to floor of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Not present
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:
Int Observations 3:
Lab Used 1:
Lab Used 2:
Lab used 3:

COMMENTS

***** GE1 *****

FIRE/RESIDENTIAL STRUCTURE

GE1, AND STATION ONE UNITS ARRIVED ON SCENE TO A 2 STORY HOUSE W/ SMOKE SHOWING FROM THE FRONT OF THE STRUCTURE ON THE FIRST FLOOR LIGHT SMOKE ON THE SECOND FLOOR.GB1 IN COMMAND AS WALNUT COMMAND. UPON FIRE ATTACK FIRE WAS LAPPING OUT A FRONT LIVING ROOM WINDOW, W/ FIRE OVERHEAD UPON ENTRY THROUGH FRONT DOOR.FIRE WAS KNOCKED DOWN AND CONFINED TO THE FIRST FLOOR LIVING AREA W/ A PRIMARY SEARCH COMPLETED.GM1, AND AT-3 ASSISTED ON THE FIRST FLOOR, WHILE GE6 AND GE3 ACESSED THE SECOND FLOOR TO HANDLE. SEARCH AND EXTENSION. GT1 PROVIDED VENTILATION.INVESTIGATOR- CAPT BENNETT INVESTIGATED, PROP WAS OVERHAULED, AND THEN RELEASED TO BLDG OWNER W/ A PROP RELEASE FORM COMPLETED.

CAPT T SAWYER