

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1600346  
Exposure Number: 00  
Multi-Agency IC#: A1601008  
Incident Date: 01/10/16  
Dispatch Time: 03:20:03  
Arrival Time: 03:26:02  
Controlled Time: 03:42:15  
Ending Time: 06:27:30  
First-In Company: GE2  
District: G2121  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: Telephone  
Type of Weather:  
Air Temperature: 53  
Address, CSZ: 11411 BAGGETT ST  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Ventilate  
Actions Taken 3: Salvage & overhaul  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 4  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$80,000  
Content Losses: \$5,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: 1 or 2 family dwelling  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved: 1  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin: Vehicle storage area; garage, carport  
Heat Source: Undetermined  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Unintentional  
Contributing Factors 1: Undetermined  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: Personal or household equipment, other  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source: Electrical line voltage (> 50 volts)  
Equip Portability: Portable  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status: Enclosed building  
# St Above Grnd: Occupied and operating  
# St Below Grnd: 1

## INCIDENT REPORT

-----

Main Floor Size: 0  
Fire Origin: 2500  
Extent of Flame: Vehicle storage area; garage, carport  
Number of Stories Damage Confined to room of origin  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys: None Present  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors: Present  
Detector Type: Smoke  
Det. Power Supply: Battery only  
Det. Operation: Detector operated  
Det. Effectiveness: Alerted occupants, occupants responded  
Det. Failure Reason:

-----

## COMMENTS

-----

\*\*\*\*\* GE2 \*\*\*\*\*

## FIRE STRUCTURE FIRE RESIDENTIAL

GE2 ARRIVED ON SCENE WITH FOUR AT A ONE STORY SINGLE FAMILY RESIDENCE, WE HAD AN ATTACHED GARAGE WELL INVOLVED IN FIRE. GE2 IN THE ATTACK MODE WITH A PRECONNECT, EVACUATING THE LIVING AREA AND CHECKING FOR EXTENSION. GE2 BRIEFLY ATTACKED THE FIRE FROM THE FRONT OF THE GARAGE, THEN ENTERED THE LIVING AREA FOUND NO EXTENSION AND COMPLETED A PRIMARY AND SECONDARY SEARCH. THE MAN DOOR FROM THE KITCHEN TO THE GARAGE WAS FOUND OPEN AND THE LIVING AREA WAS CHARGED WITH SMOKE ABOUT CHEST HIGH. THE GAS METER TO THE NORTH OF THE EXTERIOR OF THE GARAGE BREACHED AT SOME POINT DURING FIRE ATTACK; GAS COMPANY NOTIFIED AND RESPONDED TO THE SCENE. THE FIRE WAS KNOCKED DOWN WITHIN 20 MINUTES. PER A MALE OCCUPANT HE SMELLED AN ODOR OF SMOKE PRIOR TO THE SMOKE DETECTORS ACTIVATING, HE WENT INTO THE GARAGE TO GET THE DOG(S) AND STATED THAT HE SAW FIRE IN THE NORTHEAST CORNER OF THE GARAGE. GE1 AND GE2 INVESTIGATED THE FIRE AND FOUND COMPETING IGNITION SOURCES; ONE BEING THE WATER HEATER, THE SECOND BEING A SPACE HEATER WHICH WAS TURNED ON AT APPROXIMATELY MIDNIGHT FOR THE DOGS THAT WERE IN THE GARAGE. THE FIRE IS DETERMINED TO BE ACCIDENTAL IN NATURE. GE2 AND GT1 COMPLETED OVERHAUL TO THE FIRE AND RELEASED THE PROPERTY BACK TO THE HOMEOWNER; THE HOMEOWNER SIGNED AND WAS GIVEN A COPY OF THE RELEASE FORM. SIX PEOPLE WERE DISPLACED AND WERE NOT IN NEED OF RED CROSS. PROPERTY OWNER HAD MADE CONTACT WITH THE INSURANCE COMPANY PRIOR TO THE SCENE BEING RELEASED. GE2 COMPLETED AND RETURNING TO QUARTERS.

CAPTAIN BRENEMAN

