

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1608465
Exposure Number: 00
Multi-Agency IC#: 16-078339
Incident Date: 07/26/16
Dispatch Time: 00:05:10
Arrival Time: 00:09:50
Controlled Time: 00:35:17
Ending Time: 02:03:36
First-In Company: GE25
District: G2414
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 73
Address, CSZ: ADVANTAGE DENTAL LABORATORY, 7
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 1
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 1
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$25,000
Content Losses: \$100,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Professional supplies, services
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:

Bldgs. Involved:
Acres Burned:
On-Site Mat/Stor: Dental supplies
Area of Origin: Equipment or service area, other
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Cause undetermined after investigation
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Dental equipment, other
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Electrical, other
Equip Portability: Portable
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 200
Extent of Flame: Equipment or service area, other
Number of Stories Damage: Confined to room of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:

Int Observations 3:

Lab Used 1:

Lab Used 2:

Lab used 3:

COMMENTS

***** GE25 *****

STRUCTURE FIRE-COMMERCIAL
CE64, CE65, CT64, GT1, GM1, CB8, AND GB1 RESPONDED TO A COMMERCIAL STRUCTURE
FIRE IN A DENTAL LABORATORY OFFICE. GE25 MADE ENTRY AND EXTINGUISHED THE
FIRE WITH A 1 3/4" PRE-CONNECT HOSE LINE AND TANK WATER. OTHER UNITS ON
SCENE ASSISTED WITH RECEO AND VENTILATION. FIRE CAUSE INVESTIGATION WAS
CONDUCTED BY ENG. JACOBS AND DETERMINED TO BE UNKNOWN/ACCIDENTAL AND
POSSIBLY ELECTRICAL RELATED. AFTER OVERHAUL WAS COMPLETED, UNITS G,H, AND J
WERE RELEASED BACK TO OWNERS OR OWNERS REPS. VIA PROPERTY RELEASE FORMS.
G.G.P.D. WAS ALSO ON SCENE TO ASSIST WITH OWNER NOTIFICATIONS AND SECURITY
ISSUES. GE25 SECURED.
EDNOFF

GE25,
CAPT.