

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1611751
Exposure Number: 00
Multi-Agency IC#: A1630544 00347973 16-107737
Incident Date: 10/11/16
Dispatch Time: 20:24:57
Arrival Time: 20:28:32
Controlled Time: 20:55:01
Ending Time: 01:02:33
First-In Company: GE2
District: G2319
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 70
Address, CSZ: 9741 BIXBY AV APT L
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Fire control or extinguishment, other
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 13
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$500,000
Content Losses: \$150,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Residential, other
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:

Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin: Cooking area, kitchen
Heat Source: Heat source; other
First Item: Cooking materials, including edible mate
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Misuse of material or product, other
Contributing Factors 2:
Human Factor Cont 1: Unattended or unsupervised person
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Kitchen & cooking equipment, other
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Electrical, other
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 3

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 800
Extent of Flame: Cooking area, kitchen
Number of Stories Damage: Confined to building of origin
Minor:
Sign:
Heavy;
Extreme:

Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:
Int Observations 3:
Lab Used 1:
Lab Used 2:
Lab used 3:

COMMENTS

***** GE2 *****

STRUCTURE FIRE-RESIDENTIAL

AT 20:24 HRS GE2 RESPONDED TO 9741 BIXBY AV APT L FOR A REPORT OF A STRUCTURE FIRE. GE2 ARRIVED ON SCENE AND ACCESSED THE EAST GATE OF THE MALABAR APARTMENT COMPLEX FOR ACCESS. GE2 FOUND HEAVY SMOKE AND FIRE SHOWING FROM A SECOND FLOOR WINDOW OF A THREE STORY APARTMENT BUILDING TOWARDS THE BIXBY SIDE OF THE PARKING LOT. GE2 ACCESSED THE EAST GATE AND INITIATED AN ALLEY LAY. GE2 WENT INTO THE ATTACK MODE AND INITIATED A RESCUE EXCEPTION DUE TO THE FACT OF THE TIME OF DAY, KNOWLEDGE OF THE BUILDING WITH THE THIRD FLOOR ATTACHED TO THE SECOND FLOOR APARTMENT, AND THE HIGH VOLUME OF PEOPLE WHO LIVE IN THE COMPLEX. GE2 HAD SECOND IN COMPLETE THE WATER SUPPLY, TAKE COMMAND AND ESTABLISH 2 OUT. A WORKING FIRE ASSIGNMENT WAS ALREADY ESTABLISHED ENROUTE TO THE CALL MADE BY GB1 FROM INFORMATION BY METRO NET. GE2 SET UP FOR FIRE ATTACK AND NOTICED 3 LOUD EXPLOSIONS THAT HAPPENED. ONCE THOSE HAPPENED THE ENTIRE 2ND FLOOR WAS FULLY INVOLVED WITH EXTENSION TO THE 3RD FLOOR. GE2 MADE AN AGGRESSIVE FIRE ATTACK ON THE SECOND FLOOR AND STARTED UP TOWARDS THE 3RD FLOOR OF THE UNIT INVOLVED. GE2 WAS ASSIGNED FIRE ATTACK AND THEN REASSIGNED TO DIVISION 2. GE2, GE7 AND GE1 FF KNOCKED THE FIRE DOWN ON THE 3RD FLOOR AND WITH HELP FROM GT1 WITH VERTICAL VENTILATION THE FIRE WAS CONFINED TO THE UNIT INVOLVED. THERE WAS WATER DAMAGE TO 3 OTHER UNITS AND A DOOR WAS KICKED IN TO CHECK FOR EXTENTION TO THE AJACENT UNITS. PER FIRE INVESTIGATOR KUHLMAN THE ORIGIN OF THE FIRE WAS IN THE KITCHEN AREA AND THE CAUSE WAS UNATTENDED COOKING PER TALKING TO THE RESIDENTS WHO LIVED IN THE UNIT. DIVISION 2 WAS TAKEN OVER BY AB2 AND GE2, GE7, GE5, GE6 STARTED SALVAGE AND OVERHAUL AFTER FIRE INVESTIGATOR KUHLMAN'S INVESTIGATION. UTILIZING THE TIC OVERHAUL WAS PERFORMED BY THE REMOVAL OF DRYWALL AND THE USE OF FOAM, HOT SPOTS INSIDE THE APARTMENT THAT WERE SMOULDERING WERE PUT OUT. ONCE SALVAGE AND OVERHAUL WERE COMPLETE FAMILIES THAT WERE AFFECTED BY THE INCIDENT WERE TURNED OVER TO RED CROSS FOR FURTHER ASSISTANCE. THE CITY OF GARDEN GROVE RELEASE AND ASSUMPTION OF RISK OF REAL PROPERTY AFTER EMERGENCY RESPONSE FORM WAS COMPLETED AND SIGNED BY THE MALABAR APARTMENTS MANAGER LAURA CARRILLO WHO WOULD BE IN CONTACT WITH THE PROPERTY MANAGEMENT COMPANY. THE MANAGER WAS GIVEN AN EXPLANATION OF WHAT HAPPENED AND WHAT NEEDED TO BE DONE WITH THE BUILDING PER THE FORM. THE STRUCTURE WAS SECURED BY DAN TREJO OF HARBRO BOARD UP COMPANY WHICH THE MALABAR APARTMENTS CONTRACT WITH PER THE MANAGER. GE2 WAS THEN COMPLETE.

CAPTAIN PARDOEN

