

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1608909
Exposure Number: 00
Multi-Agency IC#:
Incident Date: 08/05/16
Dispatch Time: 21:33:24
Arrival Time: 21:39:30
Controlled Time:
Ending Time: 22:27:49
First-In Company: GE3
District: G2524
Incident Type: Passenger vehicle fire
Mutual Aid: None
Method of Alarm: Telephone
Type of Weather:
Air Temperature: 72
Address, CSZ: WB 22 FY / E OF HARBOR BL
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Investigate
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 2
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$10,000
Content Losses: \$1,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Highway or divided highway
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

EMERGENCY MEDICAL SERVICE

Number of Patients:
Billing Care:
Status:
Transported to:
Patients Trans - Fire:
Patients Trans - Amb:

COMMENTS

***** GE3 *****

FIRE

RESPONDED ON A VEHICLE FIRE LOCATED ON THE RIGHT SHOULDER OF THE EB 22FWY JUST EAST OF HARBOR. ON ARRIVAL, GE3 NOTICED A WELL INVOLVED VEHICLE FIRE. GE3 UTILIZED THE BUMPER LINE TO EXTINGUISH THE FIRE, AND VEHICLE OWNER AND OCCUPANTS WERE FOUND TO HAVE 0 INJURIES.

THE DRIVER OF THE VEHICLE STATED SHE SMELLED SMOKE COMING FROM THE VEHICLE AIR VENTS AND THOUGHT IT WAS FROM OUTSIDE. A LITTLE BIT LATER, ANOTHER VEHICLE TOLD HER SMOKE WAS COMING FROM UNDER THE HOOD OF THE VEHICLE. WHEN THE DRIVER PULLED TO THE SHOULDER OF THE FREEWAY, SHE NOTICED SMOKE AND FIRE COMING FROM UNDER THE VEHICLES HOOD.

UPON HEARING THE DRIVERS STATEMENT AND ON FURTHER INVESTIGATION, THE FIRE APPEARED TO HAVE ORIGINATED IN THE ENGINE COMPARTMENT OF THE VEHICLE BY AN UNKNOWN CAUSE.

CAPTAIN TRUHILL

