

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1613994  
Exposure Number: 00  
Multi-Agency IC#: 16-129892 H1619082  
Incident Date: 12/08/16  
Dispatch Time: 03:02:53  
Arrival Time: 03:07:55  
Controlled Time:  
Ending Time: 04:11:15  
First-In Company: GE4  
District: G2211  
Incident Type: Building fire  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:  
Air Temperature: 49  
Address, CSZ: 5931 SANTA CATALINA AV  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Provide advanced life support (ALS)  
Actions Taken 3:  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 3  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 2  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$5,000  
Content Losses: \$100  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: 1 or 2 family dwelling  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved: 1  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin Other  
Heat Source: Multiple heat sources including multiple  
First Item: Soft goods, wearing apparel, other  
Confined to Object: Fabric, textile, fur, other  
Material Type: Insufficient Information  
Factor Causing: Unintentional  
Contributing Factors 1: None  
Contributing Factors 2:  
Human Factor Cont 1: Asleep  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: None  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## STRUCTURE FIRE

Type:  
Status: Enclosed building  
# St Above Grnd: Occupied and operating  
# St Below Grnd: 1

## INCIDENT REPORT

-----

Main Floor Size: 0  
Fire Origin: 1800  
Extent of Flame: Other  
Number of Stories Damage: Confined to object of origin  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys: None Present  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors: Present  
Detector Type: Undetermined  
Det. Power Supply: Undetermined  
Det. Operation: Undetermined  
Det. Effectiveness:  
Det. Failure Reason:

-----

## COMMENTS

-----

\*\*\*\*\* GE4 \*\*\*\*\*

## FIRE STRUCTURE FIRE CAPT RUHMAN

GE4 CM17 CE17 CT17 GE5 GB1 RESPONDED TO A ONE STORY HOUSE WITH SMOKE SHOWING. GE4 WENT INTO ATTACK MODE WITH RESCUE EXEMPTION AND INITIATED A PRIMARY SEARCH. E4 EVACUATED 3 PEOPLE AND FOUND A SMOLDERING FIRE NEAR A FIRE PLACE. GE4 EXTINGUISHED THE FIRE WITH A GREEN LINE AND ASSIGNED CT17 TO EVACUATE SMOKE. CM17 TRANSPORTED A FEMALE PT C/O SOB FROM SMOKE INHALATION TO UCI HOSP WITH ALS CARE VIA CARE AMB. GE5 TRANSPORTED A MALE PT C/O SOB DUE TO SMOKE inhalation TO UCI HOSP WITH ALS CARE VIA CARE AMB. REMAINDER OF THE ASSIGNMENT WAS CANCELLED. NO EXTENSION WAS FOUND AND THE PROPERTY WAS RELEASED BACK TO THE RESIDENT WITH A PROPERTY RELEASE. CAUSE WAS FOUND TO BE AN UNATTENDED FIRE IN A FIREPLACE THAT CAUGHT A NEARBY RUG ON FIRE. GE4 COMPLETE.