

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1700919
Exposure Number: 00
Multi-Agency IC#: 01700871 A1702161
Incident Date: 01/21/17
Dispatch Time: 09:06:57
Arrival Time: 09:11:45
Controlled Time: 09:19:55
Ending Time: 13:01:42
First-In Company: GE6
District: G2326
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 48
Address, CSZ: 12092 BAYPORT ST APT 4
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 4
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$130,000
Content Losses: \$25,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Multifamily dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Undetermined
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Cause undetermined after investigation
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 2

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 400
Extent of Flame: Undetermined
Number of Stories Damage: Confined to floor of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:
Int Observations 3:
Lab Used 1:
Lab Used 2:
Lab used 3:

COMMENTS

***** GE6 *****

FIRE. STRUCTURE FIRE. GE6 RESPONDED TO THE REPORTED LOCATION FOR A CLOSET FIRE AT A RESIDENTIAL APARTMENT BUILDING. AE3 ARRIVED ON SCENE FIRST AND WENT INTO FIRE ATTACK REPORTING SMOKE SHOWING. GGPD OFFICERS WERE ON SCENE AND HAD HELPED EVACUATE RESIDENTS PRIOR TO FIRE DEPARTMENT ARRIVAL. GE6 ESTABLISHED "BAYPORT IC" AND PROVIDED 2 OUT. OE6 WAS ASSIGNED BY IC TO BACK UP FIRE ATTACK. GT1 WAS ASSIGNED VENTILATION GROUP AND GM1 WAS ATTACHED WITH THEM TO HANDLE UTILITIES. GB1 ARRIVED ON SCENE AND TOOK OVER COMMAND. GE6 WAS REASSIGNED TO EXPOSURE GROUP. AE3 DECLARED KNOCKDOWN OF THE FIRE IN THE INVOLVED UNIT #4. OE6 CREW CHECKED UNIT #3 AND FOUND NO EXTENSION. OVERHAUL WAS HANDLED BY GT1, OT1, GM1, GE1, AND GE6 PERSONNEL. GE3 WAS RELEASED ALONG WITH OE6, OT1, AND AE3. GGFDF FIRE INVESTIGATOR JACOBS HANDLED INVESTIGATION AND INTERVIEWED RESIDENTS. GARDEN GROVE BUILDING OFFICIAL ARRIVED ON SCENE AND SURVEYED DAMAGE TO THE UNITS AND RED TAGGED ALL FOUR UNITS 1-4 UNINHABITABLE FOR RESIDENTS. APARTMENT OWNER: MIKE DUENO WAS CONTACTED BY PHONE AND NOTIFIED OF THE INCIDENT AND DAMAGE TO THE UNITS. APARTMENT OWNER STATED HE CONTACTED HIS INSURANCE AND HAD A BOARD UP COMPANY ENROUTE TO SECURE THE APARTMENT BUILDING AND UNITS. RED CROSS ARRIVED ON SCENE AND PROVIDED TEMPORARY HOUSING ARRANGEMENTS TO THE DISPLACED RESIDENTS ALONG WITH WATER AND SNACKS. AFTER INVESTIGATION AND INTERVIEWS WERE COMPLETED THE CAUSE OF FIRE WAS UNDETERMINED. RESIDENTS WERE ALLOWED TO RETURN TO THEIR UNITS AND RETRIEVE NEEDED ITEMS TO LIVE AT TEMPORARY HOUSING ARRANGEMENTS. RESIDENTS WERE INSTRUCTED TO SECURE THEIR UNITS WHEN DONE RETRIEVING NEEDED ITEMS. A PROPERTY RELEASE WAS FILLED OUT BY GE6 AND SIGNED BY TENANT: RICARDO LOPEZ OF THE INVOLVED UNIT #4. EXCELSIOR RESTORATION INC. ARRIVED ON SCENE AND WAS GOING TO BEGIN CLOSING UP AND SECURING THE STRUCTURE. GE6 COMPLETE.

CAPT. RUZICKA

