

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1704243
Exposure Number: 00
Multi-Agency IC#: A1710520 17-039444 00121115 01704154 00121139
Incident Date: 04/09/17
Dispatch Time: 11:53:55
Arrival Time: 11:56:16
Controlled Time: 13:31:10
Ending Time: 19:18:22
First-In Company: GM1
District: G2119
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 54
Address, CSZ: 11192 RAINIER CT
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 6
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 5
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$500,000
Content Losses: \$50,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Residential, other
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved: 1
Acres Burned:
On-Site Mat/Stor:
Area of Origin Undetermined
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Factors contributing to ignition, other
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: Undetermined
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source: Electrical, other
Equip Portability: Stationary
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 1400
Extent of Flame: Undetermined
Number of Stories Damage: Confined to building of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: Undetermined
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Unknown
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GM1 *****

STRUCTURE FIRE-HOUSE FIRE

INCIDENT #G1704243

GE2 RESPONDED TO 11192 RAINIER CT FOR A REPORT OF A STRUCTURE FIRE. AT6 AND AE6 WERE ONSCENE FIRST AND REPORTED A SINGLE STORY HOUSE THAT WAS FULLY INVOLVED. GE2 WAS ASSIGNED TO DIVISION ALPHA TO ASSIST AE6 WITH FIRE ATTACK. THE FIRE WAS KNOCKED DOWN WITH LARGE HOSELINES INPLACE AND GOOD VERTICLE VENTILATION. GE2 THEN PULLED HOSELINES INSIDE AND THEN WAS ABLE TO KNOCK DOWN THE REST OF THE FIRE INSIDE THE HOUSE. MULTIPLE UNITS FROM GARDEN GROVE FIRE, ANAHEIM FIRE, ORANGE CITY FIRE, AND OCFA WERE UTILIZED TO STABILIZE THE INCIDENT. ONCE THE FIRE WAS KNOCKED DOWN GE2 WAITED FOR INVESTIGATOR STROHM TO ARRIVE TO THE SCENE BEFORE OVERHAUL WAS STARTED. INVESTIGATOR STROHM FOUND IT TO BE UNDETERMINED AS THE CAUSE INITIALLY. MORE INFO WITH THE ARSON REPORT WILL BE AVAILABLE FROM INVESTIGATOR STROHM. ONCE THE INVESTIGATION WAS COMPLETED GE2 AND GT1 PERFORMED SALVAGE AND OVERHAUL OF THE ENTIRE HOUSE AS WELL AS THE BACK YARD. GE2 MADE CONTACT WITH THE PROPERTY OWNER AND HAD THEM SIGN THE RELEASE AND ASSUMPTION OF RISK OF REAL PROPERTY AFTER EMERGENCY RESPONSE FORM TO CLAIM THE PROPERTY. THE FIRE IS STILL UNDER INVESTIGATION PER INVESTIGATOR STROHM. PROPERTY DAMAGE WAS ESTIMATED AT \$500,000 AND CONTENT DAMAGE WAS ESTIMATED AT \$50,000.

CAPTAIN PARDOEN

