INCIDENT REPORT

_____ INCIDENT ______ Fire Department: Garden Grove Fire Department Incident Number: G1704481 Exposure Number: 00 A1711088 Multi-Agency IC#: Incident Date: 04/15/17 Dispatch Time: 00:14:05 Arrival Time: 00:20:08 Controlled Time: 00:35:52 Ending Time: 01:23:20 First-In Company: GE6 District G2224 Incident Type: Fire, other Mutual Aid: None Method of Alarm: Telephone Type of Weather: Air Temperature 55 12271 BLUEBELL AV Address, CSZ: Census Tract: Fire Haz Sev Zone: Medium RESOURCES & CASUALTIES ______ Actions Taken 1: Extinguishment by fire service personnel Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: 2 #Apparatus Resp Trk: #Apparatus Resp Med: #Apparatus Resp Oth: Fire Svs Injury: 1 0 Fire Svs Fatal: Non-FS Injury: 0 Non-FS Fatal: PROPERTY & STUDIES _____ \$5,000 Property Losses: Content Losses: \$1,000 Property Value: Contents Value: Insurance Co: Building Ins:

1 or 2 family dwelling

Detector did not alert occupants

Mixed Prop Use:

Property Use:

Detector

INCIDENT REPORT

Hazmat Rel: None Critical Inc: Special Studies: FIRE/ EXPLOSION SITUATION Residential Units: Bldgs. Involved: 0 Acres Burned: On-Site Mat/Stor: Area of Origin Attic: vacant, crawl space above top story, cupola Heat Source: Hot or smoldering object, other First Item: Undetermined Confined to Object: Natural product, other Material Type: Insufficient Information Factor Causing: Unintentional Contributing Factors 1: Electrical failure, malfunction, other Contributing Factors 2: Human Factor Cont 1: None Human Factor Cont 2: Human Factor Cont 3: Age Sex Equip Involved: Electrical wiring, other Equip Brand: Equip Model: Equip Serial Number: Equip Year: Equip Power Source: Electrical, other Equip Portability: Stationary Mobile Prop Inv: Mobile Prop Type: Mobile Prop Make: Mobile Prop Model: Mobile Prop Year: Mobile Prop Lic. Plate: Mobile Prop Lic. State: Mobile Prop VIN Number: Mobile Prop Stolen?: Suppression Factors:

COMMENTS

**** GE6 ****

STRUCTURE FIRE

INCIDENT REPORT

GE6 RESPONDED TO A SINGLE STORY HOUSE WITH LIGHT SMOKE COMING FROM THE ATTIC VENTS, GE6 FOUND A WIRE FROM THE CLOSET AREA THAT BURNT THE TOP PLATE AND CHARRED THE RAFTER GOING TO A BEDROOM LIGHT. GE6 OPENED A HOLE IN THE FRONT BEDROOM TO EXPOSE THE BURNT RAFTER.

CAPT ACOSTA

						-
	·					
		ı	,			The second secon
						A A R. C.
			•			
						A THE PARTY OF THE
						>