

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1705087
Exposure Number: 00
Multi-Agency IC#: 17-047115 H1706789 00145317
Incident Date: 04/29/17
Dispatch Time: 04:33:19
Arrival Time: 04:37:57
Controlled Time: 04:51:30
Ending Time: 06:37:08
First-In Company: GE7
District: G2719
Incident Type: Special outside fire, other
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 73
Address, CSZ: 9741 READING AV
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Salvage & overhaul
Actions Taken 3: Fire control or extinguishment, other
#Apparatus Resp Engine: 3
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 2
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$10,000
Content Losses: \$2,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: 1 or 2 family dwelling
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved:
Acres Burned: 0
On-Site Mat/Stor:
Area of Origin
Heat Source: Hot or smoldering object, other
First Item:
Confined to Object:
Material Type:
Factor Causing:
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: Asleep
Human Factor Cont 2: Possibly impaired by alcohol or drugs
Human Factor Cont 3:
Age
Sex
Equip Involved:
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status:
St Above Grnd:
St Below Grnd:

INCIDENT REPORT

Main Floor Size:
Fire Origin:
Extent of Flame:
Number of Stories Damaged By Flame
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys:
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors:
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

ARSON

Agency Name:
Address:
City:
State:
Zip:
Phone:
Their Case No.
Their ORI:
Their FID:
Their FDID:
Case Status:
Avail of Mat:
Motivation Factors 1:
Motivation Factors 2:
Motivation Factors 3:
Group Involvement 1:
Group Involvement 2:
Group Involvement 3:
Entry Method:
Extent of Fire:
Container:
Ignit Device:
Fuel:
Other Inv Info 1:
Other Inv Info 2:
Other Inv Info 3:
Property Ownership:
Int Observations 1:

INCIDENT REPORT

Int Observations 2:

Int Observations 3:

Lab Used 1:

Lab Used 2:

Lab used 3:

COMMENTS

***** GE7 *****

FIRE

GE7 RESPONDED TO A 2 STORY HOUSE WITH MODERATE SMOKE FROM THE FRONT DOOR. GE7 INITIATED FIRE ATTACK UTILIZING A RESCUE EXEMPTION AS TWO OCCUPANTS STATED THAT THEIR UNCLE WAS INSIDE. GE7 FOUND THE FIRE IN THE REAR PATIO AREA, WHERE THE UNCLE WAS FOUND WITH THE GARDEN HOSE. MODERATE SMOKE DAMAGE WAS FOUND INSIDE THE RESIDENCE. FIRE WAS EXTINGUISHED AND GE4 FIRE ARSON INVESTIGATOR WAS CALLED TO THE SCENE. PROPERTY WAS RELEASED TO THE OWNERS SON. THE CAUSE OF THE FIRE WAS INVESTIGATED BY ARSON INVESTIGATOR EDNOFF. THE CAUSE REMAINS UNDETERMINED OR ACCIDENTAL IN NATURE.

CAPT FELLNER