

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1709133
Exposure Number: 00
Multi-Agency IC#: A1723300 17-086257
Incident Date: 08/07/17
Dispatch Time: 18:20:18
Arrival Time: 18:28:11
Controlled Time: 18:45:33
Ending Time: 20:02:17
First-In Company: GE6
District: G2425
Incident Type: Passenger vehicle fire
Mutual Aid: None
Method of Alarm: Telephone
Type of Weather:
Air Temperature: 82
Address, CSZ: 12842 PALM ST
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 3
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 1
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$30,000
Content Losses: \$1,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Vehicle parking area
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved:
Acres Burned:
On-Site Mat/Stor: Autos, trucks, buses, recreational vehic
Area of Origin Engine area, running gear, wheel area
Heat Source: Heat from powered equipment, other
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Failure of equipment or heat source
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv: Involved in ignition and burned
Mobile Prop Type: Automobile, passenger car, ambulance, ra
Mobile Prop Make: Honda
Mobile Prop Model: Accord
Mobile Prop Year: 2013
Mobile Prop Lic. Plate: 7APL650
Mobile Prop Lic. State: CA
Mobile Prop VIN Number: unk
Mobile Prop Stolen?: N
Suppression Factors: None

COMMENTS

***** GE6 *****

Fire - Structure Fire

INCIDENT REPORT

GE6 responded to the above address for structure fire. Upon arrival GE6 found heavy smoke coming from the parking structure of the apartment complex. GE6 went into the attack mode, initiated a primary search and started extinguishing the fire. GE3 came on scene and established command and two-out. GB1 arrived on scene shortly after and took command from GE3, assigned GLF-1 to vent group and AE3 to back up fire attack. Fire was quickly knocked down by fire personnel. Fire was confined to a single vehicle in the rear of the parking structure. Once scene was secure it was released back to the owner's representative. No injuries to civilians or fire personnel.

The fire was investigated by Captain/ Arson Investigator Kuhlman. The fire was confined to the engine compartment of the vehicle. The cause of the fire was unspecified mechanical failure in the engine compartment. Owner of the vehicle stated that he had a gasket valve adjustment recently done to the car at Honda World in the City of Westminster.

Captain Trenholm