INCIDENT REPORT

INCIDENT ______ Fire Department: Garden Grove Fire Department Incident Number: G1709053 Exposure Number: 00 Multi-Agency IC#: Incident Date: 08/05/17 18:31:58 Dispatch Time: Arrival Time: 18:36:31 Controlled Time: Ending Time: 19:08:02 First-In Company: GE1 District G2421 Incident Type: Mutual Aid: Mobile property (vehicle) fire, other None Method of Alarm: Telephone Type of Weather: Air Temperature 79 Address, CSZ: 10901 STANFORD AV Census Tract: Fire Haz Sev Zone: Medium RESOURCES & CASUALTIES Actions Taken 1: Extinguishment by fire service personnel Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: 1 #Apparatus Resp Trk: #Apparatus Resp Med: 0 #Apparatus Resp Oth: 0 Fire Svs Injury: 0 Fire Svs Fatal: 0 Non-FS Injury: 0 Non-FS Fatal: PROPERTY & STUDIES Property Losses: \$10,000 \$400 Content Losses: Property Value: Contents Value: Insurance Co: Building Ins:

Church, mosque, synagogue, temple, chape

Mixed Prop Use: Property Use:

Detector

INCIDENT REPORT Hazmat Rel: None Critical Inc: Special Studies: FIRE/ EXPLOSION SITUATION Residential Units: Bldgs. Involved: Acres Burned: On-Site Mat/Stor: Engine area, running gear, wheel area Area of Origin Heat Source: Undetermined First Item: Undetermined Confined to Object: Material Type: Unintentional Factor Causing: Contributing Factors 1: Electrical failure, malfunction, other Contributing Factors 2: Human Factor Cont 1: None Human Factor Cont 2: Human Factor Cont 3: Age Sex Equip Involved: None Equip Brand: Equip Model: Equip Serial Number: Equip Year: Equip Power Source: Equip Portability: Not involved in ignition, but burned Mobile Prop Inv: Mobile Prop Type: Mobile Prop Make: Mobile Prop Model: Mobile Prop Year: Mobile Prop Lic. Plate: Mobile Prop Lic. State: CA Mobile Prop VIN Number: Mobile Prop Stolen?: Suppression Factors:

COMMENTS

**** GE1 ****

VEHICLE FIRE

INCIDENT REPORT

GE1 RESPONDED TO 10901 STANFORD AVE FOR A VEHICLE FIRE IN A PARKING LOT. GE1 WENT INTO FIRE ATTACK AND PUT OUT THE VEHICLE FIRE. GE1 FOUND THAT THE FIRE STARTED IN THE ENGINE COMPARTMENT AND SPREAD INTO THE CAB. GE1 FOUND THE OWNER AND THE OWNER STATED THAT HE HAD REPLACED HIS CAR BATTERY 3 HOURS PRIOR. ONCE THE FIRE WAS PUT OUT GE1 HAD THE OWNER GET WITH GGPD TO SET UP A TOW FOR THE VEHICLE. GE1 WAS THEN COMPLETE.

MAKE:TOYOTA MODEL: SIENNA COLOR: SILVER LIC:6TAY658

CAPTAIN PARDOEN