

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1709053
Exposure Number: 00
Multi-Agency IC#:
Incident Date: 08/05/17
Dispatch Time: 18:31:58
Arrival Time: 18:36:31
Controlled Time:
Ending Time: 19:08:02
First-In Company: GE1
District: G2421
Incident Type: Mobile property (vehicle) fire, other
Mutual Aid: None
Method of Alarm: Telephone
Type of Weather:
Air Temperature: 79
Address, CSZ: 10901 STANFORD AV
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2:
Actions Taken 3:
#Apparatus Resp Engine: 1
#Apparatus Resp Trk: 0
#Apparatus Resp Med: 0
#Apparatus Resp Oth: 0
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$10,000
Content Losses: \$400
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Church, mosque, synagogue, temple, chape
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved:
Acres Burned:
On-Site Mat/Stor:
Area of Origin Engine area, running gear, wheel area
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Electrical failure, malfunction, other
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv: Not involved in ignition, but burned
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State: CA
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

COMMENTS

***** GE1 *****

VEHICLE FIRE

INCIDENT REPORT

GE1 RESPONDED TO 10901 STANFORD AVE FOR A VEHICLE FIRE IN A PARKING LOT. GE1 WENT INTO FIRE ATTACK AND PUT OUT THE VEHICLE FIRE. GE1 FOUND THAT THE FIRE STARTED IN THE ENGINE COMPARTMENT AND SPREAD INTO THE CAB. GE1 FOUND THE OWNER AND THE OWNER STATED THAT HE HAD REPLACED HIS CAR BATTERY 3 HOURS PRIOR. ONCE THE FIRE WAS PUT OUT GE1 HAD THE OWNER GET WITH GGPD TO SET UP A TOW FOR THE VEHICLE. GE1 WAS THEN COMPLETE.
MAKE:TOYOTA MODEL: SIENNA COLOR: SILVER LIC:6TAY658

CAPTAIN PARDOEN