INCIDENT REPORT

INCIDENT Fire Department: Garden Grove Fire Department Incident Number: G1506153
Exposure Number: 00 Exposure Number: Multi-Agency IC#: Incident Date: 05/30/15 Dispatch Time: Arrival Time: 06:36:16 06:43:32 Controlled Time: Ending Time: 07:39:45 First-In Company: GE5 District G2114 Water problem, other Incident Type:
Mutual Aid: None Telephone Method of Alarm: Type of Weather: Air Temperature 61 Address, CSZ: 11330 MARKON DR Census Tract: Fire Haz Sev Zone: Medium RESOURCES & CASUALTIES ______ Actions Taken 1: Shut down system Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: 0 #Apparatus Resp Trk: 0 #Apparatus Resp Med: 0 #Apparatus Resp Oth: 1 Fire Svs Injury: 0 0 Fire Svs Fatal: Non-FS Injury: Non-FS Fatal: PROPERTY & STUDIES Property Losses: Content Losses: Property Value: Contents Value: Insurance Co: Building Ins: Mixed Prop Use:

Manufacturing, processing

Property Use:

Detector

| TM | CT | DEN | סידון | FD | ORT |
|-------|----|-----|-------|--------|-------------------|
| T 1.A | -1 | תמע | 1 T T | . Li E | σ_{Γ} |

| Hazmat Rel: Critical Inc: Special Studies: | None |
|--|----------|
| | COMMENTS |
| | |

**** GE5 ****

SERVICE-INVESTIGATION

GE5
ENCOUNTERED A SPRINKLER ACTIVATION IN A FURNITURE WAREHOUSE/WOODSHOP DUE TO
A POSSIBLE TABLESAW/EQUIPMENT FIRE OUT P.T.A. GE5 SHUT DOWN THE SPRINKLER
SYSTEM AND SECURED THE PROPERTY AFTER MULTIPLE ATTEMPTS TO CONTACT THE
BUŞINESS OWNER BY G.G.P.D. AND GE5 FAILED. (PHONE WAS NOT ANSWERED). ADJACENT
BUSINESS WAS ADVISED TO NOTIFY THE SPRINKLER CO. TO RESPOND TO PUT THE
SYSTEM BACK IN SERVICE BEFORE CONTINUING OPERATIONS. NO ALARM CO. WAS
MONITORING THE SYSTEM. GE5, G.G.P.D., AND PUBLIC WORKS DEPT. ALL SECURED
AFTER COMPLETION.

CAPT. EDNOFF