

Garden Grove Fire Department

Station: **G05**Shifts Or Platoon: **B**

Location:
Location: 8242 CENTRAL AVE
Garden Grove CA 92640

Lat/Long: N 33° 46′ 12.01″ W 117° 59′ 7.78″

Location Type: 1 - Street address Map Page: 798A7 Incident Type:

131 - Passenger vehicle fire

FDID: 30035

Incident #: **2017-711785** Exposure ID: **27704720**

Exposure #: 0

Incident Date: **10/16/2017**Dispatch Run #: **F172890417**

Report Completed by:	Nguyen , Thanh	ID: 167	Date: 10/18/2017
Report Reviewed by:	Nguyen , Thanh	ID: 167	Date: 11/07/2017
Report Printed by:	Guardi, Lisa	ID: 4433	Date: 11/7/2017 Time: 16:39

Structure Type:	Property Use: 41	9 - 1 or 2 fa	amily dwelling			
Automatic Exting	guishment System P	resent: 🗆 [Detectors Present:	Cause of	Ignition: Cause undetermined affinestigation	er
Aid Given or Rec	eived: None	Primary act	tion taken: 11 - I	Extinguis	shment by fire service personnel	
Losses	Pre-Incident Val	ues				
Property:	Property:		Civilian Injuries:	0	Fire Service Injuries:	0
Contents:	Contents:		Civilian Fatalities:	0	Fire Service Fatalities:	0
Total:	Total:		Total Casualties:	0	Total Fire Service Casualties:	0
Total # of appar	atus on call:		1 Total	# of perso	onnel on call:	4

Narrative from dispatch:	**	8		
NARRATIVE (2)			· · · · · · · · · · · · · · · · · · ·	
Narrative Title: Fire - Vehicle			-	
Narrative Author: Nguyen, Thanh				
Narrative Date: 10/18/2017 07:47:53			e e	
Narrative Apparatus ID: GE5				
Narrative:				
GE5 arrived on scene to find a car in a driveway of a garden hose. GE5 forced entry into the engine compa stated that his car had a sensor problem, and had not undetermined.	irtment with a power	red saw, and extinguis	shed the fire. The owner	
Capt. Nguyen				

Unit	GE5	
Type:	Engine	a series and an
Use:	Suppression	
Response Mode:	()	
# of People	** manufacturing agreement	
Alarm	10 /16/2017 23:25:49	
Dispatched	10 /16/2017 23:26:00	
Enroute	10 /16/2017 23:27:22	
Arrived	10 /16/2017 23:33:24	***************************************
Cancelled	/ / ; ;	
Cleared Scene	10 /16/2017 23:59:00	
In Quarters	/ / : :	
In Service		

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Engine area, running gear, wheel area	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	remain a secondario (i.). Tendo por servicio seni intervisio) (filoso dell'intervisio) especiale (i.).
Type Of Material	Undetermined	Cause Of Ignition	Cause undetermined after investigation
Factor Contributing To Ignition	Mechanical failure, malfuncti	on, other	
Human Factors Contributing	None	especialis, prignistitation politica es clamatiqu. Mais cillia piladellilla a Pina diPhindita cilvilladi fa Admir (Cilu	partie of their differ a party interesting the party difference and their technique and describe in 3 animals and a second secon
Mobile Property Involve And Type	Not involved in ignition, but burned	Mobile Property Type	Automobile, passenger car, ambulance, race car
Mobile Property Make	Mazda	Mobile Property Year	2004
Mobile Property Model	Tribute	License Plate	4YTY890
State	CA	VIN	

ARSON	=	
Agency Name	Agency Address	Agency Phone

PEOPLE PERSON 1			,
Telephone Number	6573406632	Involvement	Caller
Name	T-MOBILE (877) 653-7911	Date of Birth	
Address	8062 GARDEN GROVE BLVD CA 00000-	unkaalete van avaage are nima maaraneelema aleer van de een maaleergele principle op o n [†] dool begroepe olde	inga yayaga Mandidajanga,galabi-yilis salishan desillabig yarapika sidi kalis-dilibir dilibir kalishifi delibi

CUSTOM FIELDS FORM		•
What happened?	We provided fire and rescue service	

Member Making Report (Captain Thanh Nguyen):	
Supervisor (Captain Thanh Nguyen):	