

Garden Grove Fire **Department** 

Station: G05

Location:	
CITY OF WESTMINSTER	
ORANGE COUNTY CA 00000	

Lat/Long: S 1° 0′ 0″ W 1° 0′ 0"

Location Type: 1 - Street address

Incident Type:

137 - Camper or recreational vehicle (RV) fire

FDID: 30035

Incident #: 2018-812130 Exposure ID: 35162447

Exposure #: 0

Date: 10/29/2018 Time: 12:51

Incident Date: 10/13/2018 Dispatch Run #: F182860168

<u> </u>			
Report Completed by: Rie	th , Mike K	<b>ID:</b> 2903	Date: 10/13/2018
Report Reviewed by: No	t Reviewed		

**ID:** 4433

Structure T	ype: Structur	e type, o	ther Prop	erty Use:	965 - Vehic	le parki	ng ar	ea	
Automatic	Extinguishment	System P	resent: 🗆	Detectors	s Present:	Cause o	f Ignit	ion: Cause undetermined after investigation	ir
Aid Given o	or Received:	None	Primary a	ction take	n: <b>11 - E</b>	xtingui	shme	nt by fire service personnel	
Losses		Pre-I	ncident V	alues					
Property:	\$1,500.00	Proper	rty: <b>\$2,</b> 0	00.00	Civilian Inj	uries:	0	Fire Service Injuries:	0
Contents:	\$500.00	Conter	nts: <b>\$50</b>	0.00	Civilian Fat	alities:	0	Fire Service Fatalities:	0
Total:	\$2,000.00	Total:	\$2,!	500.00	Total Casu	alties:	0	Total Fire Service Casualties:	0
Total # of	apparatus on ca	nll:			1 Total i	f of pers	onnel	on call:	4

## Narrative from dispatch:

**Report Printed by:** 

[10/13/18 12:45:12] OCFA HAS CHANGED THE PRIORITY TO PRIORITY\_10

Guardi, Lisa

[10/13/18 12:45:09] OCFA HAS CLOSED CALL 18-113120

[10/13/18 11:54:31 M027] DUPE INC 168/171

[10/13/18 11:49:32] [9] DUPLICATE CALL APPENDED TO INCIDENT AT 11:49:30

[10/13/18 11:48:21] [8] RV ON FIRE BACK PARKING LOT>> SMOKE & FLAMES FROM ROOF>> UNK IF SOMEONE

INSIDE>> NEAR CONCRETE TYPE 1 BLDG>>

[10/13/18 11:47:27] [7] A CELLULAR RE-BID HAS OCCURRED, CHECK THE ANI/ALI VIEWER FOR DETAILS

## NARRATIVE (2)

Narrative Title: FIRE

Narrative Author: Rieth, Mike

Narrative Date: 10/24/2018 16:26:57

Narrative Apparatus ID: GE5

## Narrative:

GROVE ENGINE 5 RESPONDED ON A REPORTED VEHICLE FIRE LOCATED TO THE REAR OF 7422 GARDEN GROVE BLVD WHICH IS A U-HAUL BUSINESS, TO FIND A MOTOR HOME THAT WAS HEAVILY INVOLVED WITH FIRE. ACCORDING TO U-HAUL, THIS VEHICLE WAS THE PROPERTY OF GINA WEST AND BILL SHOWERS WITH A LICENSE PLATE OF ILJU099 AND VIN OF JT5RN55DXE5009321. GE5 EXTINGUISHED THE FIRE USING A PRECONNECT HANDLINE. A SECOND MOBILE HOME VEHICLE THAT WAS PARKED NEXT TO THE ORIGINALLY INVOLVED VEHICLE WAS ALSO DAMAGED BY FIRE. THIS VEHICLE U-HAUL STATED WAS OWNED BY A PERSON NAMED SABRINA WITH A LICENSE PLATE OF 723 TRT AND A VIN OF 32MH40677CH57093. THIS SECOND VEHICLE SUFFERED EXTERIOR FIRE DAMAGE AS WELL AS SOME INTERIOR INSULATION DAMAGE AND SMOKE DAMAGE. BOTH VEHICLES WERE SEARCHED THOROUGHLY FOR OCCUPANTS WITH NONE FOUND. ACCORDING TO THE U-HAUL MANAGER ON SIGHT, BOTH VEHICLES HAVE BEEN PARKED AT THIS SPOT LONG TERM AND IT WAS HIS BELIEF THAT THEY WERE NOT OPERABLE. LARGE AMOUNTS OF BELONGINGS WERE FOUND IN THE ORIGINAL VEHICLE INCLUDING FUEL STORAGE CONTAINERS. MANAGEMENT ON SIGHT ALSO STATED THAT TRANSIENTS HAVE BEEN KNOWN TO FREQUENT THESE VEHICLES AND LIVE IN THEM AT NIGHT. DO TO THE EXTENSIVE FIRE DAMAGE TO THE FIRST VEHICLE, IT WAS DETERMINED THAT NO CAUSE OF ORIGIN COULD BE DETERMINED.

10/24 CONTACT WAS MADE WITH UHAUL MANAGEMENT IN REGARDS TO VIEWING THE SECURITY CAMERA LOCATED ON SIGHT AT THE TIME OF THE INCIDENT BUT THE MANAGER ON DUTY WAS UNABLE TO VIEW IT. CONTACT WAS MADE LATER TO POSSIBLY VIEW THE SECURITY CAMERA AND MANAGER ON DUTY MARYLIN WHITE (951-407-6976) STATED THAT THE CAMERA THAT COVERED THAT AREA WAS NON FUNCTIONING. MANAGER WHITE ALSO STATED THAT A REVIEW OF OTHER CAMERAS AT THE FACILITY STARTING AT 0600 ON FROM THAT DAY SHOWED NO ABNORMAL ACTIVITY IN THE AREA PRIOR TO THE FIRE BEING REPORTED.

APPARATUS	
Unit	GE5
Туре:	Engine
Use:	Suppression
Response Mode:	0
# of People	4
Alarm	10 /13/2018 11:47:00
Dispatched	10 /13/2018 11:47:05
Enroute	10 /13/2018 11:47:28
Arrived	10 /13/2018 11:50:31
Cancelled	/ / : :
Cleared Scene	10 /13/2018 12:30:00
In Quarters	/ /
In Service	
Number Of People not on apparat	us: 0

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Operator/passenger area of transportation equipment	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause undetermined after investigation
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	None		
Mobile Property Involve And Type	Not involved in ignition, but burned	Mobile Property Type	Mobile home
Mobile Property Make	Other Make	Mobile Property Year	
State	CA	VIN	JT5RN55DXE5009321

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service
Was this patient homeless?	Not applicable
Fire Incident - What happened?	We investigated - company officer determined cause

PERSONNEL ON CALL				
Name	Personnel Rank	Role(s)	Apparatus	
Jacobs, Michael	Engineer		GE5	
Page, Anthony J	Firefighter / Paramedic		GE5	
Rieth, Mike K	Captain		GE5	
Williams, Gregory D	Firefighter / Paramedic		GE5	