

Garden Grove Fire Department

Station: G02 Shifts Or Platoon: C

i rocation:	
13100 GILBERT ST # 52	
GARDEN GROVE CA 92844	ı

Lat/Long: N 33° 46′ 21.9″ W 117° 57' 59,29"

Location Type: 1 - Street address Map Page: 798C6

Incident Type: 111 - Building fire

FDID: 30035

Incident #: 2019-902711 Exposure ID: 38232413

Exposure #: 0

Incident Date: 03/02/2019 Dispatch Run #: F190610316

Report Completed by:	Kleibacker , Mat	thew C	ID: 3007	Date: 03/02/2019	
Report Reviewed by:	Kleibacker , Matt	thew C	ID: 3007	Date: 03/02/2019	
Report Printed by:	Guardi, Lisa	ID: 4433	Date	: 3/12/2019 Time : 10:16	

Structure Typ	e: Enclose c	l building	Property I	Jse: 429 - Multi	fam	ily dwe	lling	
Automatic Ex	tinguishment	System Pro	esent: 🗆	Detectors Present		Cause o	of Ignition: Failure of equipment source	or heat
Aid Given or I	Received:	None	Primary a	ction taken:	10	- Fire c	ontrol or extinguishment, other	
Losses	Pre-Inc	ident Valu	ies					
Property:	Property:	:		Civilian Injuries:		0	Fire Service Injuries:	0
Contents:	Contents	:		Civilian Fatalities	5:	0	Fire Service Fatalities:	0
Total:	Total:			Total Casualties:	;	0	Total Fire Service Casualties:	0
Total # of ap	paratus on ca	ıll:		5 Tota	al#	of perso	nnel on call:	14

Narrative from dispatch:

2019/03/02 20:16:04

[03/02/19 20:16:04 KOPS] District: G Report No: G1902711

2019/03/02 20:38:41

[03/02/19 20:38:41 M026] INCIDENT CLOCK STOPPED: 20:38:41

2019/03/02 20:37:25

[03/02/19 20:37:25 M026] GB1 DISSOLVE COMMAND, GE2 WILL BE POINT OF CONTACT

2019/03/02 20:36:05

[03/02/19 20:36:05 M026] GB1 GE2 GE1 GT1 TO HANDLE, GE7 CANCEL

2019/03/02 20:35:47

[03/02/19 20:35:47 M026] GE2 FIRE IS OUT, NO EXTENSION, CAN HANDLE W/ GT1 AND GE1

2019/03/02 20:31:45

[03/02/19 20:31:45 M026] GE2 LIGHT FIXTURE IS SOURCE OF FIRE, LOOKS LIKE IT'S CONTAINED TO CLOSET, FIRE IS **UNDER CONTROL**

2019/03/02 20:31:16

[03/02/19 20:31:16 M026] GB1 APPEARS FIRE IS OUT, STILL TRYING TO FIND SOURCE

2019/03/02 20:31:03

[03/02/19 20:31:03 M026] INCIDENT CLOCK ACKED: 20:31:03

2019/03/02 20:31:01

[03/02/19 20:31:01 M026] IC ADV 15 MIN ON INCIDENT CLOCK

2019/03/02 20:30:40

[03/02/19 20:30:40 KOPS] INCIDENT CLOCK ELAPSED: 20:30:40

2019/03/02 20:26:36

[03/02/19 20:26:36 M026] GE2 PRIMARY ALL CLEAR, TRYING TO FIND SOURCE OF FIRE

2019/03/02 20:25:34

[03/02/19 20:25:34 M026] GE7 EXPOSURE

2019/03/02 20:24:35

[03/02/19 20:24:35 M026] GT1 VENT GROUP

2019/03/02 20:24:33

[03/02/19 20:24:33 M026] GE1 2 OUT

2019/03/02 20:24:22

[03/02/19 20:24:22 M026] GB1 GILBERT IC

2019/03/02 20:24:14

[03/02/19 20:24:14 M026] GE2 APPEARS FIRE IS OUT

2019/03/02 20:23:53

[03/02/19 20:23:53 M026] GE2 FIRE ATTACK
2019/03/02 20:23:50
[03/02/19 20:23:50 M026] GE2 CLOSET FIRE, PULLING LINE, FIRE ATTACK, PREM IS CLEAR, ALL OCCUPANTS ARE
OUTSIDE, 2ND IN GET WATER SUPPLY
2019/03/02 20:22:26
[03/02/19 20:22:26 M026] GT1 W/3
2019/03/02 20:22:17
[03/02/19 20:22:17 M026] GE1 W/3
2019/03/02 20:21:24
[03/02/19 20:21:24 M026] GE2 W/4, 2 STORY CONDO COMPLEX, NOTHING SHOWING, MAKING ACCESS

[03/02/19 20:15:40 M062] INCIDENT CLOCK STARTED: 20:15:40 FOR 15 MINUTES

NARRATIVE (2)

2019/03/02 20:15:40

Narrative Title: STRUCTURE FIRE
Narrative Author: Kleibacker, Matthew
Narrative Date: 03/02/2019 22:48:36
Narrative Apparatus ID: GE2

Narrative:

GE2 RESPONDED TO A REPORT OF A STRUCTURE FIRE AT A 2 STORY CONDO COMPLEX. GE2 ENTERED THE COMPLEX THROUGH MAN DOOR AND FOUND LIGHT SMOKE SHOWING FROM A SECOND FLOOR UNIT.. GE2 ENTERED THE SECOND FLOOR UNIT AND FOUND MODERATE SMOKE AND SMOLDERING CLOTHS IN A CLOSET. GE2 ASSUMED FIRE ATTACK AND EXTINGUISHED THE SMOLDERING CLOTHS.

AFTER REMOVING THE CLOTHS FROM THE CLOSET, GE2 FOUND A LIGHT FIXTURE BEHIND THE CLOTHS. GE2 DETERMINED THAT THE CLOTHS CAUSED THE LIGHT BULBS TO OVER HEAT AND CATCH THE CLOTHS ON FIRE.

GE2 CHECKED FOR EXTENSION IN THE ATTACK AND FOUND NO FIRE SPREAD. THE OCCUPANTS OF THE RESIDENCE WERE INSTRUCTED TO NOT OCCUPY THE RESIDENCE AND CONTACT THE HOME OWNER ABOUT REPAIRS. THEY WERE ALSO INSTRUCTED TO CONTACT THE BUILDING DEPARTMENT BEFORE THEY OCCUPY THE RESIDENCE. THE POWER WAS SHUT DOWN AND A PROPERTY RELEASE WAS SIGNED AND GE2 CLEARED THE CALL.

CAPT. KLEIBACKER

Unit	GB1	Unit	GE1
Type:	Chief officer car	Туре:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	0
# of People	i	# of People	3
Alarm	03 /02/2019 20:14:00	Alarm	03 /02/2019 20:14:00
Dispatched	03 /02/2019 20:16:04	Dispatched	03 /02/2019 20:16:04
Enroute	03 /02/2019 20:17:15	Enroute	03 /02/2019 20:16:40
Arrived	03 /02/2019 20:22:29	Arrived	03 /02/2019 20:22:14
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	03 /02/2019 20:48:08	Cleared Scene	03 /02/2019 20:52:55
In Quarters	03 /02/2019 21:13:03	In Quarters	03 /02/2019 20:59:09
In Service	03 /02/2019 20:48:08	In Service	03 /02/2019 20:52:55
Unit	GE2	Unit	GE7
Type:	Engine	Туре:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	0
# of People	4	# of People	3
Alarm	03 /02/2019 20:14:00	Alarm	03 /02/2019 20:14:00
Dispatched	03 /02/2019 20:16:04	Dispatched	03 /02/2019 20:16:04
Enroute	03 /02/2019 20:16:55	Enroute	03 /02/2019 20:17:55
Arrived	03 /02/2019 20:21:13	Arrived	03 /02/2019 20:25:07
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	03 /02/2019 21:17:34	Cleared Scene	03 /02/2019 20:39:17
In Quarters	/ / : :	In Quarters	03 /02/2019 20:47:52
In Service	03 /02/2019 21:17:34	In Service	03 /02/2019 20:39:17
Unit	GT1		
Туре:	Truck or aerial	at the state of th	
Use:	Suppression		
Response Mode:	0		
# of People	3		
Alarm	03 /02/2019 20:14:00		
Dispatched	03 /02/2019 20:16:04		
Enroute	03 /02/2019 20:17:08		
Arrived	03 /02/2019 20:22:28		
Cancelled	/ / : :		
Cleared Scene	03 /02/2019 21:09:31		
In Quarters	03 /02/2019 21:17:39	200.200	
In Service	03 /02/2019 21:09:31		

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Closet	Heat Source	Heat from powered equipment, other
Item First Ignited	Soft goods, wearing apparel, other	Fire Is Confined To Object Of Origin	
Type Of Material	Fabric, fiber, cotton, blends, rayon, wool	Cause Of Ignition	Failure of equipment or heat source
Factor Contributing To Ignition	Electrical failure, malfunction,	other	And a grant of the second of t
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Halogen lighting fixture or lamp
Equipment Power Source	Electrical, other	Equipment Portability	Stationary

Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	2	# Of Stories Below Grade	0
Square Feet	1000	Length	
Width		Floor Of Origin	2
Fire Spread	Confined to room of origin		
Minor Damage	1	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Item Contributing Most To Spread	Wearing apparel on a person	Type Of Material Contributing Most To Spread	Fabric, fiber, cotton, blends, rayon, wool
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Battery only	Detector Operation	Detector operated
Detector Effectiveness	Detector alerted occupants, occupants responded	Detector Failure Reason	

PEOPLE PERSON 1			,
Telephone Number	7148624352	Involvement	Caller
Name	SPRINT 866-398-3284	Date of Birth	
Address	7828 E ORANGETHORPE AVE GA	RDEN GROVE, CA 92844-	

PEOPLE PER	SON 2		
Is Owner	False	Business Name	
Address	13100 GILBERT S	T 52 GARDEN GROVE, CA 92844-	

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service
Was this patient homeless?	Not applicable
Fire Incident - What happened?	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Doyle, Justin D			GT1
Fellner, Steve			GE7
Henshaw, Matthew			GE1
Kleibacker, Matthew C	Captain		GE2
Lee, Josh	Firefighter / Paramedic		GE2
Marquez Jr., John M	Engineer		GE2
Maule, Cheyne C			GB1
Mellem, Travis M			GE7
Mickelsen, Mark			GT1
Noble, Grant A			GE1
Pardoen, Brent C			GE1
Scherer, Scott A			GT1
Stowe, Timothy	Firefighter / Paramedic		GE2
Thorson, Eric			GE7

Member Making Report (Captain Matthew C Kleibacker):	
Incident Reviewer (Cantain Matthew C Kleibacker):	