

Garden Grove Fire Department Station: G07

Station: **G07**Shifts Or Platoon: **A**

Location:
Location: 14144 BROOKHURST ST GARDEN GROVE CA 92843
GARDEN GROVE CA 92843

Lat/Long: N 33° 45′ 26.62″ W 117° 57′ 16.9″

Location Type: 1 - Street address Map Page: 828E2 Incident Type: 111 - Building fire

FDID: 30035

Incident #: 2019-907886

Exposure ID: **41256412**

Exposure #: 0

Incident Date: **07/07/2019**Dispatch Run #: **F191880219**

Report Completed by:	Pardoen , Brent C	ID: 3376	Date: 07/07/2019
Report Reviewed by:	Not Reviewed		
Report Printed by:	Guardi, Lisa	ID: 4433	Date: 7/23/2019 Time: 13:35

Structure Type	Structure Type: Enclosed building Property Use: 500 - Mercantile, business, other							
Automatic Ext	inguishment System Present:	Dete	ctors Pre	sent: 🗹	Cau	se of	Ignition: Unintentional	
Aid Given or R	Aid Given or Received: Automatic aid received Primary action taken: 10 - Fire control or extinguishment, other							
Losses	Pre-Incident Values							
Property:	Property:	Civ	ilian Inju	ries:		0	Fire Service Injuries:	0
Contents:	Contents:	Civ	ilian Fata	lities:		0	Fire Service Fatalities:	0
Total:	Total:	Tot	tal Casua	lties:		0	Total Fire Service Casualties:	0
Total # of app	otal # of apparatus on call:			Total #	of pe	rson	nel on call:	18

N -:-	ᄔ				:
neio	nr	ION	na	Ade	ncies
	•••			9-	

Agency Name: Orange County Fire Authority

Agency ID: 30065
Agency Type: Fire

NARRATIVE (2)

Narrative Title: STRUCTURE FIRE COMMERCIAL

Narrative Author: Rieth, Mike

Narrative Date: 07/07/2019 20:38:33

Narrative Apparatus ID: GE7

Narrative:

GE7 RESPONDED TO A COMMERCIAL STRUCTURE FIRE LOCATED AT 14140 BROOKHURST STREET IN THE CITY OF GARDEN GROVE. ON ARRIVAL GE7 NOTICED FIRE VISIBLE FROM THE ROOF OF THE 2 STORY COMMERCIAL BUILDING. ON THE ROOF IT WAS FOUND THAT A HEAT VENT WAS ON FIRE AND THE SURROUNDING ROOF AND PARAPET WAS ALSO ON INVOLVED. GE7 MADE AN ATTACK ON THE FIRE USING A HANDLINE PUTTING OUT THE FIRE ON THE ROOF. GROVE LIGHT FORCE 1 PROVIDED VERTICAL VENTILATION AND ACCESS TO THE PARAPET TO FURTHER ASSIST IN EXTINGUISHING THE FIRE. ADDITIONAL FIRE UNITS DISCOVERED SMOKE IN BOTH UNITS DIRECTLY BELOW THIS HEAT VENT AND FIRE IN THE WALL TO THE REAR OF EACH UNIT. THE FIRE WAS COMPLETELY EXTINGUISHED IN ROUGHLY 35 MINUTES. UPON INVESTIGATION OF THE AREAS INVOLVED IT WAS DETERMINED THAT THE FIRE ORIGINATED IN THE COOKING AREA LOCATED AT THE RESTAURANT ON THE BOTTOM FLOOR ADDRESSED AS 14140 BROOKHURST. FIRE DAMAGE WAS PRESENT GOING FROM THE HEATING VENT AREA AND EXTENDING ALL THE WAY TO THE ROOF LINE. PUBLIC HEALTH ARRIVED SHORTLY AND INSPECTED THE SUSPECTED AREA OF ORIGIN. THE BUILDING DEPARTMENT WAS ALSO REQUESTED AND STATED THAT THEY WOULD ARRIVE ON THE MORNING OF MONDAY JULY 8TH. THE UTILITIES WERE CUT TO THE STRUCTURE AND WAS RED TAGGED UNITL CLEARED BY THE BUILDING DEPARTMENT. THE OCCUPANTS OF THE THREE UNITS THAT WERE INVOLVED WERE CONTACTED AND SIGNED PROPERTY RELEASE FORMS. NO INJURIES OCCURED ON THE FIRE AND ALL OCCUPANTS WERE EVACUATED SAFETLY.

CAPTAIN RIETH

Unit	GB1	Unit	GE1
ype:	Chief officer car	Туре:	Engine
Jse:	Suppression	Use:	Suppression
lesponse Mode:	0	Response Mode:	()
# of People	1	# of People	3
larm	07 /07/2019 13:54:12	Alarm	07 /07/2019 13:54:12
Dispatched	07 /07/2019 13:56:03	Dispatched	07 /07/2019 13:56:03
Enroute	07 /07/2019 13:56:55	Enroute	07 /07/2019 13:56:57
Arrived	07 /07/2019 14:05:13	Arrived	07 /07/2019 14:05:21
Cancelled	/ / : :	Cancelled	/ / : : -
Cleared Scene	07 /07/2019 16:06:18	Cleared Scene	07 /07/2019 16:44:31
in Quarters	07 /07/2019 16:59:03	In Quarters	07 /07/2019 16:55:10
n Service	07 /07/2019 16:06:18	In Service	07 /07/2019 16:44:31
Init	GE3	Unit	GE7
Гуре:	Engine	Туре:	Engine
Jse:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	0
of People	3	# of People	3
Narm	07 /07/2019 13:54:12	Alarm	07 /07/2019 13:54:12
ispatched	07 /07/2019 14:16:43	Dispatched	07 /07/2019 13:56:03
nroute	07 /07/2019 14:16:43	Enroute	07 /07/2019 13:56:56
rrived	07 /07/2019 14:16:43	Arrived	07 /07/2019 13:58:35
ancelled		Cancelled	/ / :
leared Scene	07 /07/2019 16:07:18	Cleared Scene	07 /07/2019 16:59:47
n Quarters	07 /07/2019 16:14:09	In Quarters	07 /07/2019 17:32:54
n Service	07 /07/2019 16:07:18	In Service	07 /07/2019 16:59:47
nit	GLA6	Unit	GM1
ype:	Light and air unit	Туре:	ALS unit
lse:	Suppression	Use:	EMS
esponse Mode:	0	Response Mode:	0
of People	3	# of People	2
larm	07 /07/2019 13:54:12	Alarm	07 /07/2019 13:54:12
ispatched	07 /07/2019 14:10:22	Dispatched	07 /07/2019 13:56:03
nroute	07 /07/2019 14:11:57	Enroute	07 /07/2019 13:56:49
rrived	07 /07/2019 14:39:44	Arrived	07 /07/2019 14:03:19
ancelled	//::	Cancelled	/ / : : -
Cleared Scene	07 /07/2019 16:42:19	Cleared Scene	07 /07/2019 16:44:57
n Quarters	07 /07/2019 16:42:25	In Quarters	07 /07/2019 17:17:50
n Service	07 /07/2019 16:42:19	In Service	07 /07/2019 16:44:57
nit	GT1		T. Washington Co.
ype:	Truck or aerial		
se:	Suppression		
esponse Mode:	0		
of People	3		
arm	07 /07/2019 13:54:12		
spatched	07 /07/2019 13:56:03		
route	07 /07/2019 13:57:02		
rrived	07 /07/2019 14:24:07	Management of the Control of the Con	
ancelled	/ / : :	Métrics avel à rom de	
leared Scene	07 /07/2019 16:44:57	Appendix yellowaters	
n Quarters	07 /07/2019 16:51:36		
Service	07 /07/2019 16:44:57		

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Cooking area, kitchen	Heat Source	Spark, ember, or flame from operating equipment
Item First Ignited	Cooking materials, including edible materials	Fire Is Confined To Object Of Origin	
Type Of Material		Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Stove, heating
Equipment Power Source	Natural gas or other lighter- than-air gas	Equipment Portability	Stationary

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	2	# Of Stories Below Grade	0
Square Feet	5000	Length	
Width		Floor Of Origin	2
Fire Spread	Confined to building of origin	arter i State (1904) (1	
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Undetermined	Detector Operation	Detector operated
Detector Effectiveness	Detector alerted occupants, occupants responded	Detector Failure Reason	operateu
Presence OF AES	Present	Type Of AES	

PEOPLE PERSON 1	-		
Telephone Number	9095618924	Involvement	Caller
Name	GGPD/CELL	Date of Birth	
Address	14271 CORPORATE DR	R GARDEN GROVE, CA 92843-	990-90-rund 699-70-rund feld felder zum Felderum spreichtigen. "Jeder felder fen stein steine steine steine st

CUSTOM FIELDS FORM					
What happened?	We provided fire and rescue service				
Was this patient homeless?	Not applicable				
Fire Incident - What happened?	We investigated - company officer determined cause				
Fire started due to fireworks?	No				
Injury related to fireworks?	No				

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Acosta, Alberto	Captain	OR 1988-AMBQ-wysteriol (19-190-1904) - 1886-OR 1988-Ambqo Ambqo Ambqo Ambqo Ambqo Ambqo Ambqo Ambqo Ambqo Ambqo	GE3
Bell, Bradley D			GE7
Cary, Parker			GM1
Hanna, Jeff W			GE1
Howey, Shane S	Firefighter / Paramedic		GE3
Jaeger, Bill R			GE1
Knaack, Anthony			GE7
Maule, Cheyne C			GB1
Mellem, Travis M			GE1
Mickelsen, Mark			GT1
Nguyen, Son	Engineer		GE3
Rieth, Mike K			GE7
Stowe, Timothy			GM1
Strohm, Bill			GT1
Valderrama, Mario G			GT1