

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1513464  
Exposure Number: 00  
Multi-Agency IC#:   
Incident Date: 11/26/15  
Dispatch Time: 17:38:20  
Arrival Time: 17:42:38  
Controlled Time: 17:47:05  
Ending Time: 18:22:24  
First-In Company: GE6  
District: G2323  
Incident Type: Cooking fire, confined to container  
Mutual Aid: None  
Method of Alarm: Telephone  
Type of Weather:   
Air Temperature: 65  
Address, CSZ: 11732 JOHN AV  
Census Tract:   
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2: Search  
Actions Taken 3:   
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 4  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$2,000  
Content Losses: \$2,000  
Property Value:   
Contents Value:   
Insurance Co:   
Building Ins:   
Mixed Prop Use:   
Property Use: 1 or 2 family dwelling  
Detector: Detector alerted occupants

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved: 1  
Acres Burned:  
On-Site Mat/Stor:  
Area of Origin: Cooking area, kitchen  
Heat Source: Hot or smoldering object, other  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Unintentional  
Contributing Factors 1: Factors contributing to ignition, other  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: Oven, rotisserie  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source: Gas fuels, other  
Equip Portability: Stationary  
Mobile Prop Inv: None  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## COMMENTS

\*\*\*\*\* GE6 \*\*\*\*\*

FIRE- KITCHEN FIRE

INCIDENT REPORT

---

GE6 RESPONDED TO THE ABOVE ADDRESS FOR A STRUCTURE FIRE. UPON ARRIVAL, FOUND LIGHT SMOKE SHOWING FROM THE FRONT DOOR. GE6 INVESTIGATED, FOUND AN ACTIVE FIRE IN THE KITCHEN. E6 PULLED A HOSE LINE AND EXTINGUISHED THE FIRE. FIRE WAS CONFINED TO THE OVEN AREA. MINOR SMOKE AND WATER DAMAGE TO THE KITCHEN. NO INJURIES TO THE OCCUPANTS OR FIREFIGHTERS.

FIRE WAS CAUSED BY OVEN BEING IN CLEANING MODE WITH GREASE LEFT INSIDE THE OVEN. OWNER WAS ADVISED THAT THE GAS WAS SHUT DOWN TO THE PROPERTY AND THEY NEED TO CALL THE GAS COMPANY BEFORE TURNING IT BACK ON. OWNER SIGNED PROPERTY RELEASE.

CAPTAIN TRENHOLM