

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1605965  
Exposure Number: 00  
Multi-Agency IC#: 16-056855 00183730 H1608176 00183908  
Incident Date: 05/31/16  
Dispatch Time: 05:28:34  
Arrival Time: 05:34:51  
Controlled Time: 05:56:23  
Ending Time: 11:25:19  
First-In Company: GE5  
District: G2517  
Incident Type: Passenger vehicle fire  
Mutual Aid: None  
Method of Alarm: Telephone  
Type of Weather:  
Air Temperature: 0  
Address, CSZ: 8520 GLORIA AV  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel  
Actions Taken 2:  
Actions Taken 3:  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 1  
#Apparatus Resp Oth: 9  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$125,000  
Content Losses: \$100,000  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: Vehicle parking area  
Detector

## INCIDENT REPORT

-----  
Hazmat Rel: None  
Critical Inc:  
Special Studies:  
-----

## FIRE/ EXPLOSION SITUATION

-----  
Residential Units:  
Bldgs. Involved:  
Acres Burned:  
On-Site Mat/Stor: Autos, trucks, buses, recreational vehic  
Area of Origin Vehicle storage area; garage, carport  
Heat Source: Undetermined  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Cause under investigation  
Contributing Factors 1: Undetermined  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: None  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv: Involved in ignition and burned  
Mobile Prop Type: Automobile, passenger car, ambulance, ra  
Mobile Prop Make: Chevrolet  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:  
-----

## ARSON

-----  
Agency Name:  
Address:  
City:  
State:

## INCIDENT REPORT

-----

Zip:  
Phone:  
Their Case No.  
Their ORI:  
Their FID:  
Their FDID:  
Case Status:  
Avail of Mat:  
Motivation Factors 1:  
Motivation Factors 2:  
Motivation Factors 3:  
Group Involvement 1:  
Group Involvement 2:  
Group Involvement 3:  
Entry Method:  
Extent of Fire:  
Container:  
Ignit Device:  
Fuel:  
Other Inv Info 1:  
Other Inv Info 2:  
Other Inv Info 3:  
Property Ownership:  
Int Observations 1:  
Int Observations 2:  
Int Observations 3:  
Lab Used 1:  
Lab Used 2:  
Lab used 3:

-----

## COMMENTS

-----

\*\*\*\*\* GE5 \*\*\*\*\*

## FIRE

RESPONDED WITH OCFA AND GGFD UNITS TO FIRE IN APARTMENT COMPLEX INVOLVING NUMEROUS VEHICLES IN CARPORT THAT ADJOINED A 2-STORY WING. GE5 ADVANCED ATTACK LINES OFF FIRST-IN UNIT AND CONTROLLED THE FIRE IN THE CARPORT AREA. PERSONNEL CHECKED THE APARTMENTS FOR RESCUE NEEDS, CHECKED FOR EXTENSION, AND PERFORMED SALVAGE AS NEEDED. GT1 PERFORMED VERTICAL VENTILATION AND CUT BACK EAVES THAT HAD MAJOR DAMAGE FROM FIRE EXPOSURE. FIRE WAS EXTINGUISHED IN CARPORT AREA, WITH A TOTAL OF FIVE VEHICLES DESTROYED, ALONG WITH EIGHT OTHERS SUFFERING DAMAGE FROM EXPOSURE TO HEAT. CARPORT AREA WAS OVERHAULED AT COMPLETION OF INVESTIGATION. ONE MALE PT WAS EXAMINED FOR INHALATION ISSUES BUT REFUSED TRANSPORT TO HOSPITAL. FIRE WAS UNDETERMINED PURSUANT TO ONGOING INVESTIGATION.

CAPT. ABRAHAMSON