

Service Request: 390574 Department: Public Works Status: CLOSED Priority: NORMAL Created at: April 20, 2015 08:30AM

Request: PREVENTIVE MAINTENANCE.

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO **Square Feet**:

Requester: Jose Vasquez Home Phone: Work Phone: Other Phone: Created by: josev

Eng. Permit: Police Num.: Fire Num.:

Total cost: \$96.80

Task #1

Status: CLOSED on April 21, 2015 10:00AM by Jose Vasquez Description: No task description Comments: VACUUMED CONTROLLER CABINET-REPLACED AIR FILTER-PERFORMED P.M. SCHEDULE-WALKED INTERSECTION-REMOVED GRAFFITI FROM CONTROLLER CABINET AND POLES.

Category: 700 SIGNAL MAINTENANCE Division: ENGR SERVICES Completed by: Jose Vasquez Total task cost: \$96.795 Assigned to: Jose Vasquez Requester contacted: ECD:

Actions: 700.26 OTHER (SEE COMMENTS), 740.1 GRAFFITI REMOVED/COVERED

Labor C	osts
---------	------

Name	Reg	OT	Total
Jose Vasquez	1.5 hours	0 hours	\$96.80
TOTAL	1.5 hours	0 hours	\$96.80



Service Request: 385738 **Department:** Public Works Status: CLOSED **Priority: NORMAL** Created at: January 13, 2015 08:30AM **Request:** PREVENTIVE MAINTENANCE. Location: HARBOR BLVD / TRASK AVE,

Requester: Jose Vasquez **Home Phone:** Work Phone: **Other Phone:** Created by: josev

Assigned to: Jose Vasquez

Requester contacted:

Public Property : NO	Eng. Permit:
Square Feet:	Police Num.:
	Fire Num.:

Total cost: \$96.80

Task #1

Status: CLOSED on January 13, 2015 10:00AM by Jose Vasquez

Description: No task description

Comments: Found ped push button not working on the SWC. Installed new push button for NB ped traffic. VACUUMED CONTROLLER CABINET-REPLACED AIR FILTER-PERFORMED P.M. SCHEDULE-WALKED INTERSECTION-REMOVED GRAFFITI FROM CONTROLLER CABINET AND POLES.

Category: 700 SIGNAL MAINTENANCE

Division: ENGR SERVICES

Completed by: Jose Vasquez

Total task cost: \$96.795

Actions: 700.14 REPLACED PED P/BUTTON ASSEMBLY, 700.26 OTHER (SEE COMMENTS), 740.1 **GRAFFITI REMOVED/COVERED**

ECD:

Name	Reg	ОТ	Total
Jose Vasquez	1.5 hours	0 hours	\$96.80
TOTAL	1.5 hours	0 hours	\$96.80



Service Request: 384553 Department: Public Works Status: CLOSED Priority: NORMAL Created at: December 10, 2014 01:57PM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: NORTHBOUND AND SOUTHBOUND STREET NAME SIGNS ARE OUT

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO **Square Feet**:

Eng. Permit: Police Num.: Fire Num.:

Total cost: \$214.88

Task #1

Status: CLOSED on December 09, 2014 02:30PM by Howard BrownDescription: INSTALLED LED TUBES IN BOTH FIXTURESCategory: 710 ST. LIGHTS/ILLUM. NAME SIGNSAssigned to: Howard BrownDivision: ENGR SERVICESRequester contacted:Completed by: Howard BrownECD:Total task cost: \$214.875Actions: 710.1 REPLACED LAMP

Name	Reg	ОТ	Total
Howard Brown	1.5 hours	0 hours	\$118.08
Jose Vasquez	1.5 hours	0 hours	\$96.80
TOTAL	3.0 hours	0 hours	\$214.88



Service Request: 381648 Department: Public Works Status: CLOSED Priority: NORMAL Created at: October 02, 2014 11:53AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: EASTBOUND AND WESTBOUND STREET NAME SIGNS ARE OUT

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO	
Square Feet:	

Eng. Permit: Police Num.: Fire Num.:

Total cost: \$143.25

Task #1

Status: CLOSED on October 02, 2014 12:01PM by Howard BrownDescription: INSTALLED 2 LED TUBES ALSO REPLACED 6 DEFECTIVE SIGN PANELSCategory: 710 ST. LIGHTS/ILLUM. NAME SIGNSAssigned to: Howard BrownDivision: ENGR SERVICESRequester contacted:Completed by: Howard BrownECD:Total task cost: \$143.25SECD:Actions: 710.1 REPLACED LAMP, 710.12 OTHER (SEE COMMENTS)

Name	Reg	OT	Total
Jose Vasquez	1.0 hours	0 hours	\$64.53
Howard Brown	1.0 hours	0 hours	\$78.72
TOTAL	2.0 hours	0 hours	\$143.25



Service Request: 380977 Department: Public Works Status: CLOSED Priority: NORMAL Created at: September 16, 2014 09:24AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: REPLACE OVER HEAD RED LED AND PAINT SIGNAL HEADS

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO Square Feet: Eng. Permit: Police Num.: Fire Num.:

Total cost: \$300.20

Task #1

Status: CLOSED on September 14, 2014 10:00AM by Howard Brown
Description: REPLACED EASTBOUND OVERHEAD RED AND GREEN LED ALSO PAINTED BOTH
OVERHEAD SIGNAL HEADS
Category: 700 SIGNAL MAINTENANCE
Category: 700 SIGNAL MAINTENANCE
Division: ENGR SERVICES
Requester contacted:
Completed by: Howard Brown
ECD:
Total task cost: \$300.2
Actions: 700.1 REPLACED LAMP
Labor Costs

Name	Reg	ОТ	Total
Howard Brown	0 hours	4.0 hours	\$300.20
TOTAL	0 hours	4.0 hours	\$300.20



Service Request: 380971 Department: Public Works Status: CLOSED Priority: NORMAL Created at: September 16, 2014 09:01AM

Request: PAINT EASTBOUND SIGNAL HEADS

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO **Square Feet**:

Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Assigned to: Howard Brown

Requester contacted:

Eng. Permit: Police Num.: Fire Num.:

Total cost: \$157.44

Task #1

Status: CLOSED on September 09, 2014 03:00PM by Howard Brown **Description**: PAINTED EASTBOUND 3 SECTION SIGNAL HEAD AND PAINTED THE 5 SECTION ALSO

ECD:

Category: 700 SIGNAL MAINTENANCE **Division**: ENGR SERVICES

Completed by: Howard Brown

Total task cost: \$157.44

Actions: 700.20 OTHER - SEE COMMENTS Labor Costs

Name	Reg	OT	Total
Howard Brown	2.0 hours	0 hours	\$157.44
TOTAL	2.0 hours	0 hours	\$157.44



Service Request: 380965 Department: Police Status: CLOSED **Priority: NORMAL** Created at: September 16, 2014 08:48AM **Request:** REPLACE EASTBOUND RED LEDS Location: HARBOR BLVD / TRASK AVE, **Public Property: NO Square Feet:**

Requester: JIM TUCKER Home Phone: Work Phone: **Other Phone:** Created by: howardb

Eng. Permit: **Police Num.**: Fire Num.:

Total cost: \$118.08

Task #1

Status: CLOSED on September 08, 2014 03:00PM by Howard Brown Description: REPLACED RED LED AND PAINTED THE 10FT LEVEL SIGNAL HEAD ON THE SOUTHEAST CORNER Category: 700 SIGNAL MAINTENANCE Assigned to: Howard Brown **Division**: ENGR SERVICES

Completed by: Howard Brown Total task cost: \$118.08 Actions: 700.1 REPLACED LAMP **Requester contacted**: ECD:

Labor Costs			
Name	Reg	OT	Total
Howard Brown	1.5 hours	0 hours	\$118.08
TOTAL	1.5 hours	0 hours	\$118.08



Service Request: 380393 Department: Public Works Status: CLOSED Priority: NORMAL Created at: September 02, 2014 08:30AM Request: PREVENTIVE MAINTENANCE. Location: HARBOR BLVD / TRASK AVE,

Public Property: NO **Square Feet**:

Requester: Jose Vasquez Home Phone: Work Phone: Other Phone: Created by: josev

Eng. Permit: Police Num.: Fire Num.:

Total cost: \$96.80

Task #1

Status: CLOSED on September 02, 2014 10:00AM by Jose Vasquez

Description: No task description

Comments: VACUUMED CONTROLLER CABINET-REPLACED AIR FILTER-PERFORMED P.M. SCHEDULE-WALKED INTERSECTION-REMOVED GRAFFITI FROM CONTROLLER CABINET AND POLES.

Category: 700 SIGNAL MAINTENANCE Division: ENGR SERVICES Completed by: Jose Vasquez Total task cost: \$96.795 Assigned to: Jose Vasquez Requester contacted: ECD:

Actions: 700.26 OTHER (SEE COMMENTS), 740.1 GRAFFITI REMOVED/COVERED

Name	Reg	OT	Total
Jose Vasquez	1.5 hours	0 hours	\$96.80
TOTAL	1.5 hours	0 hours	\$96.80



Service Request: 379295 Department: Public Works Status: CLOSED Priority: NORMAL Created at: August 11, 2014 01:39PM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: SIGNAL HEAD TURNED WRONG WAY NORTHEAST CORNER EB TO NB LEFT TURN

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO Square Feet: Eng. Permit: Police Num.: Fire Num.:

Total cost: \$78.72

Task #1

Status: CLOSED on August 07, 2014 11:00AM by Howard BrownDescription: RE ALIGNED SIGNAL HEADCategory: 700 SIGNAL MAINTENANCEAssigned to:Division: ENGR SERVICESRequester cCompleted by: Howard BrownECD:Total task cost: \$78.72Actions: 700.20 OTHER - SEE COMMENTSLabor CostsLabor Costs

Assigned to: Howard Brown Requester contacted: ECD:

NameRegOTTotalHoward Brown1.0 hours0 hours\$78.72TOTAL1.0 hours0 hours\$78.72



Service Request: 377507 Department: Public Works Status: CLOSED Priority: NORMAL Created at: July 03, 2014 08:44AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: MALFUNCTION MANAGEMENT UNIT CHECK

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO	Eng. Permit:
Square Feet:	Police Num.:
	Fire Num.:
Total cost : \$23.15	

Task #1

Status: CLOSED on July 03, 2014 06:00AM by Howard Brown Description: INSTALLED TESTED ECONOLITE MALFUNCTION MANAGEMENT UNIT # 090908758

Category: 700 SIGNAL MAINTENANCE

Division: ENGR SERVICES **Completed by**: Howard Brown

Total task cost: \$23.154

Assigned to: Howard Brown
Requester contacted:
ECD:

Actions: 700.20 OTHER - SEE COMMENTS Labor Costs

Name	Reg	OT	Total
Howard Brown	0.3 hours	0 hours	\$23.15
TOTAL	0.3 hours	0 hours	\$23.15



Service Request: 377306 **Department:** Public Works Status: CLOSED **Priority: NORMAL** Created at: June 30, 2014 09:52AM Requester: Howard Brown Home Phone: Work Phone: **Other Phone:** Created by: howardb

Request: SOUTHBOUND ON HARBOR - WALL PACK LIGHT OUT

Location: HARBOR BLVD / TRASK AVE, HARBOR UNDERPASS

Public Property: NO Square Feet:

Eng. Permit: **Police Num.**: Fire Num.:

Total cost: \$41.87

Task #1

Status: CLOSED on June 17, 2014 02:15PM by Howard Brown **Description:** REPLACED HPS LAMP Category: 710 ST. LIGHTS/ILLUM. NAME SIGNS Assigned to: Howard Brown **Division**: ENGR SERVICES ECD: Completed by: Howard Brown Total task cost: \$41.868 Actions: 710.1 REPLACED LAMP

Requester contacted:

Name	Reg	OT	Total
Howard Brown	0.3 hours	0 hours	\$23.01
Jose Vasquez	0.3 hours	0 hours	\$18.86
TOTAL	0.6 hours	0 hours	\$41.87



Service Request: 375395 Department: Public Works Status: CLOSED Priority: NORMAL Created at: May 15, 2014 07:39AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: 10FT SIGNAL TURNED WRONG WAY NORTHEAST CORNER

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO Square Feet: Eng. Permit: Police Num.: Fire Num.:

Total cost: \$38.34

Task #1

Status: CLOSED on May 14, 2014 11:30AM by Howard BrownDescription: RE-ALIGNED SIGNAL HEADCategory: 700 SIGNAL MAINTENANCEAssignedDivision: ENGR SERVICESRequesterCompleted by: Howard BrownECD:Total task cost: \$38.345ECD:Actions: 700.20 OTHER - SEE COMMENTSLabor Costs

Assigned to: Howard Brown Requester contacted: ECD:

Labor Costs			
Name	Reg	OT	Total
Howard Brown	0.5 hours	0 hours	\$38.34
TOTAL	0.5 hours	0 hours	\$38.34



Service Request: 375240 Department: Police Status: CLOSED **Priority: NORMAL** Created at: May 13, 2014 09:04AM **Request: INTERSECTION BLACKED OUT** Location: HARBOR BLVD / TRASK AVE, **Public Property: NO Square Feet**:

Requester: POLICE DISPATCH Home Phone: Work Phone: **Other Phone:** Created by: howardb

Eng. Permit: **Police Num.**: Fire Num.:

Requester contacted:

Total cost: \$147.12

Task #1

Status: CLOSED on May 07, 2014 06:00AM by Howard Brown Description: FOUND SCE WORKING ON A POLE NEAR THE INTERSECTION.POWER OUT DUE TO EDISON MAINTENANCE Assigned to: Howard Brown

ECD:

Category: 700 SIGNAL MAINTENANCE

Division: ENGR SERVICES

Completed by: Howard Brown

Total task cost: \$147.12

Actions: 700.20 OTHER - SEE COMMENTS Labor Costs

Name	Reg	OT	Total
Howard Brown	0 hours	2.0 hours	\$147.12
TOTAL	0 hours	2.0 hours	\$147.12



Service Request: 373900 Department: Public Works Status: CLOSED Priority: NORMAL Created at: April 17, 2014 08:30AM

Request: PREVENTIVE MAINTENANCE.

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO **Square Feet**:

Requester: Jose Vasquez Home Phone: Work Phone: Other Phone: Created by: josev

Eng. Permit: Police Num.: Fire Num.:

Total cost: \$94.30

Task #1

Status: CLOSED on April 17, 2014 10:00AM by Jose Vasquez Description: No task description Comments: VACUUMED CONTROLLER CABINET-REPLACED AIR FILTER-PERFORMED P.M. SCHEDULE-WALKED INTERSECTION-REMOVED GRAFFITI FROM CONTROLLER CABINET AND POLES.

Category: 700 SIGNAL MAINTENANCE Division: ENGR SERVICES Completed by: Jose Vasquez Total task cost: \$94.305 Assigned to: Jose Vasquez Requester contacted: ECD:

Actions: 700.26 OTHER (SEE COMMENTS), 740.1 GRAFFITI REMOVED/COVERED

Name	Reg	OT	Total
Jose Vasquez	1.5 hours	0 hours	\$94.30
TOTAL	1.5 hours	0 hours	\$94.30



Service Request: 373386 Department: Public Works Status: CLOSED Priority: NORMAL Created at: April 09, 2014 08:08AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: REMOVE AND REPLACE ASC/3 CONTROLLER

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO	Eng. Permit:
Square Feet:	Police Num.:
	Fire Num.:
Total cost : \$15.04	

\$15.04

\$15.04

0 hours

0 hours

Task #1

Howard Brown

TOTAL

0.2 hours

0.2 hours

Status: CLOSED on April 01, 2014 06:00AM by Howard Brown Description: REMOVED AND REPLACED ASC/3 CONTROLLER FOR SOFTWARE UPGRADE. INSTALLED ASC/3 CONTROLLER # 17177 **Category: 700 SIGNAL MAINTENANCE** Assigned to: Howard Brown **Division: ENGR SERVICES Requester contacted:** ECD: Completed by: Howard Brown Total task cost: \$15.038 Actions: 700.20 OTHER - SEE COMMENTS Labor Costs Name Reg OT Total

Printed May 24, 2017



Service Request: 369955 Department: Public Works Status: CLOSED Priority: NORMAL Created at: February 05, 2014 06:27AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: PEDESTRIAN SIGNAL RECALLING TO SIDE STREET

Location: HARBOR BLVD / TRASK AVE,

e Num.:
Num.:

Total cost: \$75.19

Task #1

Status: CLOSED on January 29, 2014 10:00AM by Howard BrownDescription: REPLACED BOTH PEDESTRIAN PUSH BUTTONS FOR PHASE 10-OKCategory: 700 SIGNAL MAINTENANCEAssigned to: Howard BrownDivision: ENGR SERVICESRequester contacted:Completed by: Howard BrownECD:Total task cost: \$75.19Actions: 700.20 OTHER - SEE COMMENTS
Labor CostsNameReqNameReqOTTotal

Name	Reg	OT	Total
Howard Brown	1.0 hours	0 hours	\$75.19
TOTAL	1.0 hours	0 hours	\$75.19



Service Request: 369383 Department: Status: CLOSED Priority: NORMAL Created at: January 23, 2014 12:12PM Requester: REMI NUNEZ-VALI-COOPER Home Phone: Work Phone: Other Phone: Created by: howardb

Request: CONNECT NORTHBOUND RIGHT TURN LOOPS

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO	Eng. Permit:
Square Feet:	Police Num.:
	Fire Num.:
Total cost : \$225.57	

Task #1

Status: CLOSED on January 23, 2014 10:30AM by Howard Brown Description: CONTRACTOR PULL IN 1 DLC FOR THE RIGHT TURN LOOPS- CONNECTED DLC IN CONTROLLER CABINET-RETUNED OK

Category: 700 SIGNAL MAINTENANCE

Division: ENGR SERVICES

Completed by: Howard Brown

Total task cost: \$225.57

Actions: 700.20 OTHER - SEE COMMENTS

Labor Costs

Name	Reg	ОТ	Total
Howard Brown	3.0 hours	0 hours	\$225.57
TOTAL	3.0 hours	0 hours	\$225.57

Assigned to: Howard Brown Requester contacted: ECD:



Service Request: 369381 Department: Public Works Status: CLOSED Priority: NORMAL Created at: January 23, 2014 11:47AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: INTERSECTION FLASHING RED ALL DIRECTIONS

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO	Eng. Permit:
Square Feet:	Police Num.:
	Fire Num.:

Total cost: \$37.59

Task #1

Status: CLOSED on January 23, 2014 06:15AM by Howard BrownDescription: MMU READING CVM-RESET CONTROLLER AND MMUCategory: 700 SIGNAL MAINTENANCEAssigned to: Howard BrownDivision: ENGR SERVICESRequester contacted:Completed by: Howard BrownECD:Total task cost: \$37.595ECD:Actions: 700.20 OTHER - SEE COMMENTSLabor Costs

Name	Reg	ОТ	Total
Howard Brown	0.5 hours	0 hours	\$37.59
TOTAL	0.5 hours	0 hours	\$37.59



Service Request: 369323 Department: Public Works Status: CLOSED Priority: NORMAL Created at: January 22, 2014 06:29AM Requester: Howard Brown Home Phone: Work Phone: Other Phone: Created by: howardb

Request: RE-TUNE VEHICLE DETECTORS NEW LOOPS INSTALLED

Location: HARBOR BLVD / TRASK AVE,

Public Property: NO **Square Feet**:

Eng. Permit: Police Num.: Fire Num.:

Total cost: \$136.84

Task #1

Status: CLOSED on January 21, 2014 02:00PM by Howard BrownDescription: RE-TUNED ALL PHASE 3 AND PHASE 8 DETECTORS-ALL OKCategory: 700 SIGNAL MAINTENANCEAssigned to: Howard BrownDivision: ENGR SERVICESRequester contacted:Completed by: Howard BrownECD:Total task cost: \$136.84SER COMMENTSActions: 700.20 OTHER - SEE COMMENTS

Name	Reg	OT	Total
Howard Brown	1.0 hours	0 hours	\$75.19
Jose Vasquez	1.0 hours	0 hours	\$61.65
TOTAL	2.0 hours	0 hours	\$136.84