

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved:
Acres Burned:
On-Site Mat/Stor: Undetermined
Area of Origin: Undetermined
Heat Source: Undetermined
First Item: Undetermined
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Undetermined
Contributing Factors 2:
Human Factor Cont 1: None
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv: Involved in ignition and burned
Mobile Prop Type: Trailer - travel, designed to be towed
Mobile Prop Make: UD
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State: CA
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

COMMENTS

***** GE1 *****

VEHICLE FIRE-TOY HAULER FIRE OUT ON ARRIVAL

INCIDENT REPORT

GE1 RESPONDED TO 11732 EUDORA LN FOR A VEHICLE FIRE. GE1 FOUND A TOY HAULER THAT HAD A FIRE IN THE SLEEPING QUARTERS PTA. GE1 HAD TO OVERHAUL CHAIRS, MATTRESSES AND CABINETS TO FIND THE AREA OF ORIGIN. GE1 FOUND THE ORIGIN TO BE IN THE AREA OF THE WATER HEATER AND THE HEATER UNDER THE SLEEPING AREA. NO OTHER DAMAGE WAS NOTED TO THE REST OF THE TRAILER INSIDE AND OUT. GE1 HAD THE OWNER SIGN A PROPERTY RELEASE AND STATED TO CONTACT THE INSURANCE COMPANY AS WELL AS KEEP EVERYONE OUT OF THE TRAILER AND LEAVE ALL CONNECTIONS DETATCHED. GE1 WAS THEN COMPLETE.

CAPTAIN PARDOEN